

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1868373
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CATB3PX028913
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT283RKSLE
		DEALER RO #	73247
		CLAIM START DATE	04/01/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	10-13-02-00-000211	Slide Out Room - Frame & Chassis/Slide Out System/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-04-01 15:47:36 :: FIND OUT WHY THE SLIDE ROOM DOES NOT WORK Extra weld in the track Took pictures. Looked inside of the underbelly and spotted where the slideroom had stopped because of the extra weld. Dropped the underbelly and removed the gas lines out of the way.Ran the slideroom out then grind down the weld. Ran the slideroom in and out. Put the underbelly backup and gas lines.			
Model#	Dlr Sub Hrs	2.50	Sub Labor Amt \$425.00	
Serial#	Appr Hrs	1.00	Appr Labor Amt \$170.00	
	Notes			
	EXCESSIVE AMOUNT REQUESTED CHANGED TO SIMILAR REPAIR TIME			

Submitted	Labor Amt	\$425.00	Approved	Labor Amt	\$170.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$425.00		Total	\$170.00

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.