



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 73247



### CUSTOMER WORK ORDER

WO #: 73247

Customer: 1000 - BASDEN'S AMERICAN  
RV -

Tag:

Author: BH

Location: 0410 CHECK WORK

Stock #: 11264

Stock Desc: 2023 TT COACHMEN

CATALINA 283RKSLE

Chassis #: 5ZT2CATB3PX028913

Serial #: 5ZT2CATB3PX028913

Mileage: 0

Licence:

Invoice #:

Date In: 01 APR 24

Promised:

Date Sched:

Completed: 03 APR 24

Warr. Date:

#### Job #1 - Warranty

COMPLAINT: FIND OUT WHY THE SLIDE ROOM DOES NOT WORK

CAUSE: Extra weld in the track

CORRECTION: Took pictures. Looked inside of the underbelly and spotted where the slideroom had stopped because of the extra weld. Dropped the underbelly and removed the gas lines out of the way. Ran the slideroom out then grind down the weld. Ran the slideroom in and out. Put the underbelly backup and gas lines.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	170.00
<b>Subtotal for Job #1:</b>			<b>170.00</b>

Parts Total:	0.00
Labour Total:	170.00
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>170.00</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 03 Apr 2024

Customer #: 1000  
BASDEN'S AMERICAN RV,

