



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73355
Promised Date:
24 APR 24

CUSTOMER WORK ORDER

WO #: 73355

Customer: 54660 - MCGILL, LOIS -
812-573-7823

Tag:

Author: PH

Location: 0429 BH TO CLOSE

Stock #: 11370

Stock Desc: 2024 TT COACHMEN

CATALINA SUMMIT SERIES 164BHX

Chassis #: 5ZT2CAEC1RK008018

Serial #: 5ZT2CAEC1RK008018

Mileage:

Licence:

Invoice #:

Date In: 12 APR 24

Promised: 30 APR 24

Date Sched:

Completed: 27 APR 24

Warr. Date: 23 APR 24

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 3 HR PDI

CAUSE: PDINTT PDI - TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Filled LP tank. Installed battery box. Tied Solar Panel Wires to frame for future use. Checked all Outside lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Checked Roof. Checked Entrance door and all compartment doors. Checked power cord. Operated stab jacks. Checked Awning. Checked all interior lights. Removed all shipping tape from Refrigerator. Checked all cabinets and drawers. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked converter output. Checked Radio. Mounted TV and Factory bracket. Checked operation of TV and Antenna. Checked all windows and blinds. Added water to fresh water tank and flushed antifreeze from all water lines and faucets. Connected to city water and filled Water Heater. Purged all air from water system. Filled all holding tanks and checked monitor panel. Performed LP drop test and set LP pressure at 10 in.wc. Checked Refrigerator, Furnace, Range, Air Conditioner and Water Heater on LP and Electric. Applied all company decals.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #BUNKFINAL - Internal

COMPLAINT: FINAL PDI NEW BUNKHOUSE

CAUSE: BUNKFIN FINAL PDI NEW BUNKHOUSE

CORRECTION: Installed new battery. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Recorded all tire serial numbers. Dumped all holding tanks. Water Heater is full and ready to camp. Retracted all stab jacks. Moved unit to wash bay area.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------

Printed On: 4/27/2024 10:44:34AM

© 2024 Integrated Dealer Systems



Customer #: 54660
MCGILL, LOIS



Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #BUNKFINAL: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: E2 10K E2 EQUALIZER HITCH

CORRECTION: Assembled hitch brackets and mounted on frame of unit.
 SETUP HITCH HIGHT AND FOUND THAT IT NEEDED A LONGER DROP BAR. INSTALLED A LONGER DROP BAR AND ADJUSTED HITCH HIGHT. HOOKED UP TO TRAILER AND ADJUSTED AS NEEDED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C
14-2931	90-02-4300 EQUALIZER ADJ HITCH SHANK	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #BCWV - Internal

COMPLAINT: BRAKE CONTROL & WIRING - VAN, SUV & CAR

CORRECTION: TRYED TO INSTALL THE BRAKE CONTROL AND FOUND THAT THE BRAKE LIGHTS WORK THROUGH THE PCM. I COULD NOT USE ANY OF THE WIRING FOR THE SIGNAL WIRE. WE HAVE TO USE A BLUETOOTH BRAKE CONTROL AND I RAN A CHARGE WIRE TO THE NEW 7-WAY I INSTALLED ON THE REAR OF THE SUV. I MOVED THE 4-WAY ON TOP OF THE 7-WAY AND MOUNTED BOTH ON THE REAR. ADDED A BREAKER UNDER THE HOOD FOR THE CHARGE WIRE AND TESTED THE 7-WAY OUTPUT. IT IS WORKING AS IT SHOULD.

Labor

Code	Description	Mechanic	Total
BCWV	BRAKE CONTROL & WIRING - VAN, SUV &	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
14636	7WAY PLASTIC CAR END	1.00	N/C	N/C
19-1441	16-3030 30A CIRCUIT BREAKER	1.00	N/C	N/C
51180	CURT ECHO WIRELESS BRAKE CONTROL	1.00	N/C	N/C
72-2535	58000 CURT RECEIVER 7 WAY BRKT	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #BCWV: 0.00

Job #PARTS - Internal

COMPLAINT: RHINO FLEX SEWER HOSE

CORRECTION: PUT IN UNIT



W/O: 73355
Promised Date: 30 APR 24



Customer #: 54660
MCGILL, LOIS



Parts

Part #	Description	Qty	Price	Total
39390	39390 20' RHINO X SEWER HOSE KIT	1.00	N/C	N/C

Subtotal for Job #PARTS: 0.00

Job #1 - Warranty

COMPLAINT: USB AT THE BED ON THE DOOR SIDE IS NOT WORKING

CAUSE: USB OUTLET BY BED DOES NOT WORK (CURB SIDE)

CORRECTION: Removed outlet from wall mounting. Positive wire was pulled out of back of receptical. Installed new USB charging outlet. Checked operation.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	68.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00

Parts

Part #	Description	Qty	Price	Total
F100130007	CHARGER, DUAL USB (2 PORTS) 5V BLACK	1.00	5.46	5.46

Subtotal for Job #1: 73.46

Job #2 - Warranty

COMPLAINT: THE FACTORY TV WILL NOT FIT ON WALL BRACKET. BRKT INSTALLED AT FACTORY.

CAUSE: FACTORY TV WILL NOT FIT ON WALL BRACKET

CORRECTION: Factory mounted TV bracket mounted too close to front shelf and would not go into wall mounted bracket. Removed wall bracket and remounted 3/4 in to the right. Remounted at this location. TV now mounts into wall bracket.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	17.00

Subtotal for Job #2: 17.00

Parts Total: 5.46
Labour Total: 85.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 90.46

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Apr 2024

