

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73433
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 28173 - CHRIS LIPKING
Address: 3400 LUIGS RD. WADESVILLE, IN

47638

Phone: 812-459-6361

Stock Number: 11308 - 2024 APEX 264RKS 5ZT2CXR6RS047045

VIN: 5ZT2CXR6RS047045 HIN: SER#: 5ZT2CXR6RS047045

Mileage: 0 Work Order Comp: 30 APR 24

Auth. No: Dealer #:

Warr. Date: 25 APR 24 Work Order Date: 20 APR 24 Inv #: 403745

WO # Job # Description JOB INFORMATION

73433 4 MISSING FIREPLACE REMOTE ***ROBBED FROM #RS047006 SHOWROOM***

73433 2 SLIDE LED LIGHTS NOT WORKING
lights dont work in slideroom
noticed fuse was blown in fuse box installed new fuse and turned
on light switch and fuse blew,took down lights tocheck wiring
,took off light switch and check wiring and it was good ,cut off
lights and switch to do continuity check on wires and found their
was a short in hot and ground side,tried to pull wires and they
were stuck,next had to pull tim work down and drop down ceiling
panel and wall panel to get to wires,found screw was in hot and
groung side togetherpulled screw outside out of top metal trim
and it made wires loose,pulled down wires from inside and you can
see screw hole through wires in pictures,pulled wires out and
fixed them,added wires to make them longer.hooked up wires on
both lights and switch and mounted switch and lights,pulled
staples from trim and pamel boards then restapled everything.and
filled in holes and rehung blind,we took it off to make sure
screw was not in wires.

73433 3 BATHROOM SINK SLOW TO DRAIN
bathroom sink draining slow
took pipes apart and pushed object through tail piece and it was
faucet aerator in drain pipe,screwed back on to faucet and now it
drains good.installed pipes back in place.

Claim : 73433

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
73433      5      FURNANCE NOT WORKING
                furnance dont work
                turned on furnance and ac would click but furnance wouldnt come
                on,had to unscrew both recliners and move them to get to furnance
                wires,had no power in ac for furnance wires,chased wires from
                furnance through cabinets around corner under stove into ref
                area,then took out ceiling light and chased wires checked voltage
                and none in ceiling,checked under stove and i had voltage,chased
                wire under ref and found wires had come out of crimp,recrimped
                wires and it works now,had to put everything back together,all
                good.

```

```

*****
Part No      Job#   Description      PARTS      Qty      Price      Total
*****
F100366415      4      REMOTE ONLY FOR 30" LUMENEX FIREP  1.00      6.65      6.65

```

```

*****
Lab Code Job# Description      LABOUR      Hrs      Rate      Total
*****
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      2      MISC LABOUR CODE (EXTERNAL)      1.40      170.00      238.00
Z990      2      MISC LABOUR CODE (EXTERNAL)      0.60      170.00      102.00
Z990      2      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      3      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      1.00      170.00      170.00

```

```

*****
Excode      Job#   Description      EXTRAS      Qty      Price      Total
*****
FRT          4      UPS-FIREPLACE REMOTE      1.00      17.30      17.30

```

```

Parts Total:      6.65
Labour Total:      544.00
Sublet Total:      0.00
Extras Total:      17.30

```

>>>> Claim Total: 567.95

Customer Signature: _____

Date: _____