

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

CLAIM STATUS Authorized
CLAIM 1903599
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CXR6RS047045
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 220 / 220A
ITEM # APTT264RKS
DEALER RO # 73433
CLAIM START DATE 05/01/2024
CLAIM END DATE 01/01/1900

Labor rate: \$170.00

OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code

40-196-24-11-001297

Operational Description

Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-05-01 16:12:18 :: SLIDE LED LIGHTS NOT WORKING
lights dont work in slideroom noticed fuse was blown in fuse box installed new fuse and turned on light switch
and fuse blew, took down lights to check wiring ,took off light switch and check wiring and it was good ,cut off
lights and switch to do continuity check on wires and found their was a short in hot and ground side,tried to pull
wires and they were stuck, next had to pull tim work down and drop down ceiling panel and wall panel to get to
wires, found screw was in hot and groung side together pulled screw outside out of top metal trim and it made
wires loose, pulled down wires from inside and you can see screw hole through wires in pictures, pulled wires out
and fixed them, added wires to make them longer. hooked up wires on both lights and switch and mounted
switch and lights,pulled staples from trim and pamel boards then restapled everything. and filled in holes and
rehung blind,we took it off to make sure screw was not in wires.

Model#

Dlr Sub Hrs

2.00

Sub Labor Amt \$340.00

Serial#

Appr Hrs

2.00

Appr Labor Amt \$340.00

Notes

Labor

Line# 2

Operation Code

60-138-24-00-001535

Operational Description

Drainage Lines - Plumbing/Drainage System/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-05-01 16:13:47 :: BATHROOM SINK SLOW TO DRAIN.
bathroom sink draining slow took pipes apart and pushed object through tail piece and it was faucet aerator in
drain pipe, screwed back on to faucet and now it drains good. installed pipes back in place.

Model#

Dlr Sub Hrs

0.20

Sub Labor Amt \$34.00

Serial#

Appr Hrs

0.20

Appr Labor Amt \$34.00

Notes

Labor

Line# 3

Operation Code

30-307-01-00-000920

Operational Description

Fireplace Remote Control - Interior/Fireplace/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-05-01 16:14:42 :: MISSING FIREPLACE REMOTE\ install
remote

Model#

Dlr Sub Hrs

0.00

Sub Labor Amt \$0.00

Serial#

Appr Hrs

0.00

Appr Labor Amt \$0.00

Notes

Labor

Line# 4

Operation Code

40-196-24-11-001297

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-05-01 16:15:32 :: vFURNANCE NOT WORKING furnace dont work turned on furnace and ac would click but furnace wouldnt come on,had to unscrew both recliners and move them to get to furnace wires,had no power in ac for furnace wires,chased wires from furnace through cabinets around corner under stove into ref area,then took out ceiling light and chased wires checked voltage and none in ceiling,checked under stove and i had voltage,chased wire under ref and found wires had come out of crimp,recrimped wires and it works now,had to put everything back together,all good.

Operational Description

Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical

Model#

Serial#

Notes

Dlr Sub Hrs

1.80

Sub Labor Amt

\$306.00

Appr Hrs

1.00

Appr Labor Amt

\$170.00

Submitted	Labor Amt	\$680.00	Approved	Labor Amt	\$544.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$680.00		Total	\$544.00

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.