

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1894023
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAEC2RK007119
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT164BHX
ROGER K FENWICK		DEALER RO #	73441
7901 W FRANKLIN RD		CLAIM START DATE	04/23/2024
Evansville, IN 47712		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	03/05/2024	WARRANTY EXPIRATION DATE	03/05/2025

Claim Line Details

Labor

Line# 1	Operation Code SB-456-01-00-004506	Operational Description 51-1722 – ROOF MOUNT SOLAR INLET (AURORA & CATALINA) - INSPECTION AND PERFORM REMEDY - Technical Service Bulletin/Sealant/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-04-23 16:12:53 :: ROOF SEALANT. RECALL. SOLAR 51-1722 ROOF MOUNT SOLAR INLET REMOVED OLD SOLAR MOUNT AND INSTALLED NEW AND SEALED WITH DICOR.	
Model#	Dir Sub Hrs	Sub Labor Amt
	0.50	\$85.00
Serial#	Appr Hrs	Appr Labor Amt
	0.50	\$85.00
	Notes NEED PHOTO OF CORRECTION IN THE NOTES YOU STATE THAT DICOR WAS USED? THE REPAIR IS FOR YOU TO USE ALPHA SELF LEVEL yea i went to the tech and he used alpha AUTHORIZED AS REQUESTED	

Labor

Line# 2	Operation Code 20-66-02-17-000672	Operational Description Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-04-23 16:14:21 :: THE MAIN DOOR IS DIFFICULT TO CLOSE FROM THE INSIDE. IT CLOSES GOOD FROM THE OUTSIDE, BUT NOT THE INSIDE. Tightened up Hadley. And adjusted the striker plate.	
Model#	Dir Sub Hrs	Sub Labor Amt
	0.20	\$34.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$34.00
	Notes	

Labor

Line# 3	Operation Code RC-003-22-00-004526	Operational Description 24V254, 2024-214 - CHARGE LINE OVERCURRENT PROTECTION - INSPECTION AND REMEDY - Recall/Electrical/Rewire/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-04-23 16:18:14 :: THE CHARGE LINE MAY NOT HAVE OVER CURRENT PROTECTION SWAPPED WIRES ON BREAKER FOR RECALL.	
Model#	Dir Sub Hrs	Sub Labor Amt
	0.20	\$34.00

Serial#

Appr Hrs

0.20

Appr Labor Amt \$34.00

Notes

AUTHORIZED AS REQUESTED

Submitted

Labor Amt	\$153.00
Parts & Freight	\$0.00
Total	\$153.00

Approved

Labor Amt	\$153.00
Parts & Freight	\$0.00
Total	\$153.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.