

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1906673
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CA4B0RX031690
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT39MKTS
WAYNE R BRASHEAR		DEALER RO #	73457
1505 E ST CLAIR ST		CLAIM START DATE	05/04/2024
Vincennes, IN 47591		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	04/25/2024	WARRANTY EXPIRATION DATE	04/25/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	70-147-01-00-001766	TV Antenna Base Plate - Appliances/Television/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-05-04 15:02:09 :: ANTENNA BROKE APART FROM DELIVERY FROM FACTORY TV ANTENNA BROKEN OFF FROM DELIVERY FROM FACTORY INSTALLED NEW ON THE CAMPER			
	Model#	Dlr Sub Hrs	1.50	Sub Labor Amt \$255.00
	Serial#	Appr Hrs	1.00	Appr Labor Amt \$170.00
	Notes			
	EXCESSIVE AMOUNT REQUESTED			
	CHANGED TO FLAT RATE			

Labor

Line# 2	Operation Code	Operational Description		
	60-138-24-00-001535	Drainage Lines - Plumbing/Drainage System/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-05-04 15:05:05 :: KITCHEN SINK GREY TANK LEAKING KITCHEN SINK GREY TANK LEAKING Water leaking out the underbelly. Cut access hole below grey tank. Water is everywhere below tank. Opened dump valve on tank and drained. Turned water on again. As soon as it was turned on it was leaking. Removed panel under kitchen sink to see drain pipe. Found that down pipe from kitchen sink was not connected to drain pipe at floor line. Drain pipe was never glued in place. Cut out shelf so that drain pipe could be inserted in fitting. Glued pipe and fitting together. Checked for leak. No leak at this time. Remounted cabinet doors. Retaped access door in underbelly.			
Model#		Dlr Sub Hrs	2.00	Sub Labor Amt \$340.00
Serial#		Appr Hrs	2.00	Appr Labor Amt \$340.00
	Notes			
	AUTHORIZED AS REQUESTED			
	INSTALL ISSUE			

Labor

Line# 3	Operation Code	Operational Description		
	30-99-24-00-001015	Mini-Blind - Interior/Soft Goods/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-05-04 15:06:04 :: KITCHEN BLIND LOOKS CROOKED			
	Adjusted blind in kitchen.			
Model#		Dlr Sub Hrs	0.05	Sub Labor Amt \$8.50
Serial#		Appr Hrs	0.05	Appr Labor Amt \$8.50
	Notes			

Labor
Line# 4

Operation Code
30-101-36-00-001076

Operational Description
Hinged Passage Door - Interior/Interior Doors/Touch Up/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-05-04 15:09:13 :: BATHROOM DOOR OPENS WHEN WALKING BY ADDED WOOD BEHIND THE DOOR STRIKER PLATE HAD TO BEND TAB A LITTLE AND TRIMMED OUT THE PLASTIC.

Model#

Dlr Sub Hrs 0.10

Sub Labor Amt \$17.00

Serial#

Appr Hrs 0.10

Appr Labor Amt \$17.00

Notes

Submitted	Labor Amt	\$620.50	Approved	Labor Amt	\$535.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$620.50		Total	\$535.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.