



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73481
Promised Date:
24 MAY 24

CUSTOMER WORK ORDER

WO #: 73481

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: PH

Location: 0524 BH TO CLOSE

Stock #: 11376

Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 310BR

Chassis #: 4YDTSGR22R7104351

Serial #: 4YDTSGR22R7104351

Mileage: 0

Licence:

Invoice #:

Date In: 25 APR 24

Promised: 31 MAY 24

Date Sched:

Completed: 28 MAY 24

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New trailer PDI

CORRECTION: Checked water and plumbing systems

Checked electrical system

Checked 12vdc system

Checked LP system

Checked LP system

Leak test...passed

Checked interior and exterior

Checked lights

Checked running gear

Remove silicone sealer and tape from awning

Use fill stick to cover and blend in scratches on the bathroom door.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

SCRATCH ON THE FRIDGE DOOR

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	0.00
Z990	MISCELLANEOUS REPAIR	JH	0.00
Z990	MISCELLANEOUS REPAIR	JH	34.00



Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 73481
Promised Date: 31 MAY 24



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts

Part #	Description	Qty	Price	Total
652725	Refrigerator - Refer Door - Replacem	1.00	306.68	306.68

Other Services

Code	Description	Qty	Price	Total
FRT	UPS - REFER DOOR	1.00	77.71	77.71

Subtotal for Job #1: 418.39

Job #2 - Warranty

COMPLAINT: STAPLE HOLES IN THE BACK OF THE DINNETTE

CAUSE: Staple holes in back of dinette

CORRECTION: Use filstick to fill and blend color in the back of dinette where staple holes are.
Fill and blend with filstick to cover staple holes.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	0.00
Z990	MISCELLANEOUS REPAIR	JH	17.00

Subtotal for Job #2: 17.00

Job #3 - Warranty

COMPLAINT: SCRATCHES ON BATHROOM DOOR

CAUSE: Repair scratches on the bathroom door

CORRECTION: Use filsticks to fill and blend scratches in bathroom door.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00

Subtotal for Job #3: 34.00

Parts Total: 306.68
Labour Total: 85.00
Sublet Total: 0.00
Extras Total: 77.71
WORK ORDER TOTAL: 469.39

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 May 2024

