



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73507
Promised Date:
06 MAY 24

CUSTOMER WORK ORDER

WO #: 73507

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: BH
Location: 0506 DELIVERY 0504 BH
SENT IN PREAUTH

Stock #: 11270
Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 200RLC
Chassis #: 4YDTSGJ29R7100132
Serial #: 4YDTSGJ29R7100132
Mileage: 0
Licence:

Invoice #:
Date In: 27 APR 24
Promised: 06 MAY 24
Date Sched:
Completed: 30 APR 24
Warr. Date: 27 APR 24

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT FINAL PDI ON NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Remounted battery box. Shortened battery cables to fit. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 75 psi. Checked roof and sealed a few spots. Checked power cord. Checked all interior lights. Checked converter output. Added water to fresh water tank and flushed antrifreeze from water lines and faucets. Connected to city water and flushed water lines. Performed LP drop test and set LP peressure at 10 in.wc. Operated all appliances. Checked Air Conditioner. Used test TV to check all antennalocations, inside and outside. Retracted power jacks. Drained all holding tanks. Moved unit to washbay area.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
24-0146	TV1-025H SWIVEL/TILT WALL MOUNT	2.00	N/C	N/C
E222	E222 WHITE PLASTIC GRAB HANDLE	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #SWAP - Internal

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CORRECTION: STARTED WORKING ON SWAPPING CUSTOMERS HITCHWORK AND THE CUSTOMER CHANGED THERE MIND. NO LONGER TAKING UNIT.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Warranty

COMPLAINT: THE BIG REAR WINDOW IS HARD TO OPEN AND THE BOTTOM OF THE WINDOW IS BOWED

CAUSE: THE BIG REAR WINDOW IS HARD TO OPEN AND THE BOTTOM OF THE WINDOW IS



Customer #: 1000
BASDENS AMERICAN RV,



BOWED

CORRECTION: Removed window mounting screws across bottom of window. Screws across bottom were put in at an angle causing mounting frame to be bowed up. Reattached mounting ring with new screws inserted straight in to eliminate frame being bowed up.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00
Z990	MISCELLANEOUS REPAIR	DKM	0.00
Subtotal for Job #1:			34.00

Job #2 - Warranty

COMPLAINT: ON THE BOTTOM OF THE BIG REAR WINDOW THE PAPER IS PEALING OFF NEED TO GLUE IT DOWN TO MAKE SURE IT DOES NOT GET WORST

CAUSE: ON THE BOTTOM OF THE BIG REAR WINDOW THE PAPER IS PEALING OFF NEED TO GLUE IT DOWN TO MAKE SURE IT DOES NOT GET WORST

CORRECTION: Straightened wall paper and applied glue to hold area in place. Taped temp with blue tape. Removed tape after glue was dry.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	0.00
Z990	MISCELLANEOUS REPAIR	DKM	17.00
Subtotal for Job #2:			17.00

Job #3 - Internal

LABOR FOR THE TV AND HANDLE

Labor			
Code	Description	Mechanic	Total
Z990	INSTALL TV BRACKET	DKM	N/C
Z990	INSTALL SHOWER HANDLE	DKM	N/C
Subtotal for Job #3:			0.00

Parts Total:	0.00
Labour Total:	51.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	51.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 May 2024

W/O: 73507
Promised Date: 06 MAY 24



Customer #: 1000
BASDENS AMERICAN RV,

