

**Pre-Authorization**

Pre-Authorization number PA03658892 Reference no: 73518 Status: Approved Approved by navra Approved date 5/2/2024  
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGG12RW10156: 3/15/2024  
 600 E Baseline Rd  
 Evansville, IN 47725

Nu	Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
mbe	operation								
r of									
1	1200214A	Bumper, Metal	0.00	0.20	0.20		1	1.00	Complaint:REMOVE SCREWS IN JACKS WHERE THEY GO THRU BUMPER ON BOTH SIDES AND PUT BACK WHERE IT DON'T GO IN BUMPER Cause:Factory self tappers in the rear bumper, this prevents the sewer hose not to storage.  Correction:Removed the self tappers the the stab jack that go thru the rear bumper. Moved the self tappers to another spot. Took pictures of the Problem.

Pre-Authorization number PA03658892 0.20

For paper claims only use one pre-authorization number per warranty claim for  
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company