



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73519
Promised Date:
29 APR 24

CUSTOMER WORK ORDER

WO #: 73519 (Appointment Date: 29 APR 2024 - Time: 02:00pm)

Customer: 54079 - IGLEHEART, KASEY - Stock #: 11262

812-698-9297

Tag:

Author: BJW

Location: 0506 SEE IF BH CAN CLOSE
WARRANTY PORTION

Stock Desc: (11262) 2023 FOREST
RIVER CHEROKEE GREY WOLF 29TE
Chassis #: 4X4TCKE23PX161612
Serial #: 4X4TCKE23PX161612
Mileage:
Licence:

Invoice #: 403991

Date In: 29 APR 24

Promised: 30 APR 24

Date Sched:

Completed: 30 APR 24

Warr. Date: 05 OCT 23

Job #1 - Internal

COMPLAINT: CUSTOMER ADVISES THAT THERE IS A LEAK AT THE BACKSIDE OF THE WATER HEATER.

CAUSE: No problem found

CORRECTION: Filled the fresh tank 1/3 full then turned on the water pump and water heater. Opened up the kitchen faucet and let the water run. Got Ben to also inspect but neither one of us could find a leak. Went under the bed and inspected for any leaks. Tried on city water and water pump for leaks. Made sure all the water lines were tight. No further action.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THE WALL TO THE LEFT OF THE REFRIGERATOR IN THE OUTDOOR KITCHEN IS SPLITTING. IS THERE ANYTHING THAT WE CAN DO TO CORRECT THIS.

CAUSE: Wall paneling split

CORRECTION: Got some liquid nail and put in the wall then squeezed with clamps. Will let it dry overnight. After the glue was dry then taped off the area and painted black.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	34.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #2: 34.00

Job #3 - Internal

COMPLAINT: CUSTOMER ADVISES WHEN USING THE FURNACE, IT WILL HEAT TO DESIRED TEMP ONCE AND THEN IT WILL NEVER COME BACK ON.

CAUSE: No cause found



Customer #: 54079
IGLEHEART, KASEY



CORRECTION: Plugged in the shore power cord. Turned on the ac to cool the inside from sitting in the sun all day. It was 98 degrees inside the camper, will cool it down to 70 degrees then turn on the furnace to inspect. Turned on the lp tanks then turned on the furnace. Set thermostat to 80 degrees then furnace ran and shut off the furnace when temp was satisfied. Waited for furnace to shutoff the set the thermostat to 80 degrees again. Furnace ran great. Couldn't recreate the same as customer.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #3: 0.00

Job #LP - External
 COMPLAINT: FILL LP

CAUSE: Lp fill

CORRECTION: Removed the lp tank cover. The disconnected the lp lines from the lp tanks. Only fill 1-20lb. Mounted tanks down then hooked up the lp lines.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	4.00	N/C	N/C

Subtotal for Job #LP: 0.00

Parts Total: 0.00
 Labour Total: 34.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 34.00

Thank you for being a valued customer. We appreciate your business.
 All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 May 2024



Customer #: 54079
 IGLEHEART, KASEY

