

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1906597
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CANB2RU043498
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT243RBSLE
		DEALER RO #	73529
		CLAIM START DATE	05/04/2024
		CLAIM END DATE	01/01/1900
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Claim Line Details

Labor

Line# 1	Operation Code 10-17-01-00-000309	Operational Description Black Dock Bumper - Frame & Chassis/Specialty/Utility Unit/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-05-04 10:01:22 :: THE BUMMPER IS MISSING FOR THE BACK RACK FOUND BUMMPER MISSING INSTALL NEW BUMMPER	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$34.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$34.00
	Notes AUTHORIZED AS REQUESTED	

Labor

Line# 2	Operation Code 70-147-24-00-001769	Operational Description TV Coax Cable - Appliances/Television/Repair/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-05-04 10:12:43 :: TV ANTENNA BUSTER IS MISSING TV antenna booster doesn't work Repair loose connection at TV booster	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$34.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$34.00
	Notes	

Labor

Line# 3	Operation Code 60-141-19-00-001596	Operational Description Tub Surround - Plumbing/Shower, Tub Surround/Reseal/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-05-04 10:14:18 :: SHOWER SURROUND NEEDS SEALED Shower surround needs sealed. Silicone shower surround inside and out	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.30	\$51.00
Serial#	Appr Hrs	Appr Labor Amt
	0.30	\$51.00
	Notes AUTHORIZED AS REQUESTED	

Labor

Line# 4	Operation Code 20-58-01-00-000608	Operational Description Metal - Aluminum Siding, each sheet - Exterior/Metal, Aluminum Siding/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-05-04 10:15:57 :: THE METAL IS DAMAGED FROM THE MISSING BUMPER . FOUND THE BUMPER IS MISSING AND HAS DAMAGED THE METAL ON THE CAMPER NEED TO REPLACE THE METAL	
Model#	Dlr Sub Hrs	Sub Labor Amt
	4.00	\$680.00

Serial#

Appr Hrs

4.00

Appr Labor Amt \$680.00

Notes

AUTHORIZED AS REQUESTED
INSTALL ISSUE

Submitted

Labor Amt	\$799.00
Parts & Freight	\$0.00
Total	\$799.00

Approved

Labor Amt	\$799.00
Parts & Freight	\$0.00
Total	\$799.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.