



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 73529  
Promised Date:  
24 MAY 24

### CUSTOMER WORK ORDER

WO #: 73529

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag: PH - PARTS ORDERED PER BEN.  
5-13-24  
Author: PH  
Location: 0620 BH TO CLOSE

Stock #: 11382  
Stock Desc: 2024 TT COACHMEN  
CATALINA 243RBSLE  
Chassis #: 5ZT2CANB2RU043498  
Serial #: 5ZT2CANB2RU043498  
Mileage: 0  
Licence:

Invoice #:  
Date In: 30 APR 24  
Promised: 31 MAY 24  
Date Sched:  
Completed: 21 JUN 24  
Warr. Date:

#### Job #PDINTT - Internal

Transferred to BAS\*73635 on 10 MAY 24  
Estimate amount was 0.00  
PDI - NEW TRAVEL TRAILER

#### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

#### Job #1 - Warranty

COMPLAINT: THE BUMMPER IS MISSING FOR THE BACK RACK

CAUSE: FOUND BUMMPER MISSING

CORRECTION: INSTALL NEW BUMMPER

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	34.00

#### Parts

Part #	Description	Qty	Price	Total
C01303901	METAL, .024 X 16" X 96" 1MDM SL COAC	1.00	52.27	52.27
C01299075	LABEL, USA MASS LABEL INFO ( LARGE -	1.00	3.76	3.76
F100296631	COACHMENRV.COM LABEL	1.00	2.43	2.43
9337	RUBBER BUMPER FOR BAL GEAR RACK	1.00	3.77	3.77

#### Other Services

Code	Description	Qty	Price	Total
FRT	SAIA FREIGHT - METAL	1.00	368.05	368.05

Customer #: 1000  
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 464.28

Job #2 - Warranty

COMPLAINT: TV ANTENNA BUSTER IS MISSING

CAUSE: TV antenna booster doesn't work

CORRECTION: Repair loose connection at TV booster

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	34.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: SHOWER SURROUND NEEDS SEALED

CAUSE: Shower surround needs sealed.

CORRECTION: Silicone shower surround inside and out

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	51.00

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	18.22	18.22

Subtotal for Job #3: 69.22

Job #4 - Warranty

THE METAL IS DAMAGED FROM THE MISSING BUMPER

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	484.50
Z990	MISC LABOUR CODE (EXTERNAL)	BB	195.50

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECALS AND BUMPER	1.00	17.32	17.32

Subtotal for Job #4: 697.32

Parts Total: 80.45  
Labour Total: 799.00  
Sublet Total: 0.00  
Extras Total: 385.37  
**WORK ORDER TOTAL: 1,264.82**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 73529  
Promised Date: 31 MAY 24



Customer #: 1000  
BASDENS AMERICAN RV,



Date: 21 Jun 2024

Customer Signature : \_\_\_\_\_

W/O : 73529  
Promised Date: 31 MAY 24



Customer #: 1000  
BASDEN'S AMERICAN RV,



Customer Work Order

