

**aim Response**

5/15/2024  
11:03:19 am

aim: C3630227

**Non-Warranty Goodwill Adjustment**

Last Modified by: yambri

Item	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed Type	Date Of Purchase
------	---------------	-------------------	-------------	-----	----------	--------	-----------------------	------------	--------------	------------------

630227	73567	5/10/2024	5/10/2024	4YDT28B27K3248491	1194	Basden's American RV	600 E Baseline Rd Evansville, IN 47725	170.00	0.00	SA21-414	5/27/20
--------	-------	-----------	-----------	-------------------	------	----------------------	---	--------	------	----------	---------

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Denied

P sent to customer on 5873259  
Component Model: 6020      Component Serial Number: N 18 26

Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B Cause: regulator recall 21-414 Correction: took pictures and found it needed to be replaced, took off regulator with hoses and installed all new regulator and hoses, turned on tanks and used leak detector to check hoses no leaks then hooked up meter and did lp drop test for 5 min at 8 water coloum, no leaks all good. (Deking/KRV)		0.50	0.50	85.00	0.00	1	0.50	Approved

Submitted parts & sublet	28.75	Approved parts & sublet	0.00
Submitted labor & sublet	85.00	Approved labor & sublet	85.00
Submitted freight:	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
<b>Total Submitted:</b>	<b>113.75</b>	<b>Total approved:</b>	<b>85.00</b>