



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73597



CUSTOMER WORK ORDER

WO #: 73597

Customer: 7226 - GOURLEY, BOBBY L. -
812-618-6656
Tag:
Author: PH
Location: 0607 CHECK PREAUTH

Stock #: 11361
Stock Desc: 2024 TT KEYSTONE
COUGAR HALF-TON 33RLI
Chassis #: 4YDTCGR20RV505602
Serial #: 4YDTCGR20RV505602
Mileage:
Licence:

Invoice #:
Date In: 07 MAY 24
Promised:
Date Sched:
Completed: 31 MAY 24
Warr. Date: 16 MAY 24

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: final pdi

CORRECTION: did final pdi and everything on sheet, checked lp , water, electrical and all appliances.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #1 - Internal

COMPLAINT: DELIVER TO CUSTOMERS HOUSE PER CHAD

CORRECTION: CHAD SAID KW DELIVERED TO CUSTOMERS HOUSE 5 MILES

Other Services

Code	Description	Qty	Price	Total
DELIVERY	DELIVERY FEE	5.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THE RIGHT REAR RUNNING LIGHT LENS IS MISSING

CAUSE: right rear running light missing lens

CORRECTION: had to replace whole light because that is all we had, cut wires and rewired and sealed.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	17.00

Parts

Part #	Description	Qty	Price	Total
523675	523675 RED ELLIPTICAL LIGHT	1.00	2.63	2.63

Customer #: 7226
GOURLEY, BOBBY L.



Subtotal for Job #2: 19.63

W/O: 73597

Job #3 - Warranty

COMPLAINT: KITCHEN CABINET DOORS HIT

CAUSE: kitchen doors hit

CORRECTION: adjusted hinges and now they shut.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	13.60
Z990	MISCELLANEOUS REPAIR	DGH	3.40

Subtotal for Job #3: 17.00

Job #4 - Warranty

COMPLAINT: BATHROOM CABINET DOORS HIT

CAUSE: cabinet doors would not shut,

CORRECTION: adjusted doors out as far as they would go and they still hit,so i marked out hinges and chisled out wood to set back farther,installed door back and now they shut fine now.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	34.00

Subtotal for Job #4: 34.00

Parts Total: 2.63
 Labour Total: 68.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 70.63



Customer #: 7226
GOURLEY, BOBBY L.

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Jun 2024

