



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 73649  
Promised Date:  
16 MAY 24



Customer #: 54784  
BRYAN, PATRICIA



## CUSTOMER WORK ORDER

WO #: 73649

Customer: 54784 - BRYAN, PATRICIA -  
812-629-0103

Tag:

Author: BH

Location: 0530 CHECK PREAUTH

Stock #: 11360

Stock Desc: 2024 TT FOREST RIVER  
CHEROKEE WOLF DEN 16EV

Chassis #: 5ZT2CKEC3RY033134

Serial #: 5ZT2CKEC3RY033134

Mileage:

Licence:

Invoice #:

Date In: 13 MAY 24

Promised: 16 MAY 24

Date Sched:

Completed: 24 MAY 24

Warr. Date: 16 MAY 24

### Job #BUNKFINAL - Internal

COMPLAINT: FINAL PDI NEW BUNKHOUSE

CAUSE: final pdi

CORRECTION: did final and everything on paperwork,checked water,appliances,and electrical.

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | N/C   |

#### Parts

| Part # | Description                            | Qty  | Price | Total |
|--------|----------------------------------------|------|-------|-------|
| DC-24  | ADVANCE GROUP 24 DEEP CYCLE<br>BATTERY | 1.00 | N/C   | N/C   |

Subtotal for Job #BUNKFINAL: 0.00

### Job #3002 - Internal

COMPLAINT: RECEIVER - UNIVERSAL SUV

CORRECTION: INSTALLED THE UNIVERSAL RECEIVER.

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | GAH      | N/C   |

#### Parts

| Part # | Description                   | Qty  | Price | Total |
|--------|-------------------------------|------|-------|-------|
| 13386  | 13386 CURT RECEIVER CLASS III | 1.00 | N/C   | N/C   |

#### Other Services

| Code | Description   | Qty  | Price | Total |
|------|---------------|------|-------|-------|
| FRT  | FREIGHT       | 1.00 | N/C   | N/C   |
| SS   | SHOP SUPPLIES | 1.00 | N/C   | N/C   |

Subtotal for Job #3002: 0.00

### Job #BCWV - Internal

COMPLAINT: BRAKE CONTROL & WIRING - VAN, SUV & CAR

CORRECTION: INSTALLED BRAKE CONTROL AND WIRING. USED OEM TYPE HARNESS IN THE REAR FOR THE 7-WAY AND INSTALLED A NEW 7-WAY ON THE REAR. USED A OEM TYPE HARNESS



FOR THE BRAKE CONTROL. CHECKED THE 7-WAY ON THE REAR AND EVERYTHING IS WORKING AS IT SHOULD.

| Labor |                                     |          |       |
|-------|-------------------------------------|----------|-------|
| Code  | Description                         | Mechanic | Total |
| BCWV  | BRAKE CONTROL & WIRING - VAN, SUV & | GAH      | N/C   |

| Parts   |                                |      |       |       |
|---------|--------------------------------|------|-------|-------|
| Part #  | Description                    | Qty  | Price | Total |
| 14636   | 7WAY PLASTIC CAR END           | 1.00 | N/C   | N/C   |
| 72-2535 | 58000 CURT RECEIVER 7 WAY BRKT | 1.00 | N/C   | N/C   |
| 19-1441 | 16-3030 30A CIRCUIT BREAKER    | 1.00 | N/C   | N/C   |
| 17-0081 | #51120 BRAKE CONTROL           | 1.00 | N/C   | N/C   |
| 72-2407 | T-CONNECTOR 11-14 EXPLORER     | 1.00 | N/C   | N/C   |
| 81783   | 81783 92-19                    | 1.00 | N/C   | N/C   |
|         | FORD/MERCURY/LINCOLN           |      |       |       |

| Other Services |               |      |       |       |
|----------------|---------------|------|-------|-------|
| Code           | Description   | Qty  | Price | Total |
| SS             | SHOP SUPPLIES | 1.00 | N/C   | N/C   |

Subtotal for Job #BCWV: 0.00

#### Job #SWAYB - Internal

COMPLAINT: SWAY CONTROL INSTALLED AND WELD PLATE ON TO THE DRAW BAR

CAUSE: sway b

CORRECTION: measured for sway b and installed plate on frame, drilled holes and secured. SETUP BALL BAR PIN AND CLIP. I HAD TO NOTCH THE BAR TO GET IT TO FIT IN THE SUV. I ADDED THE SWAY-B BALL TO THE BAR.

| Labor |                        |          |       |
|-------|------------------------|----------|-------|
| Code  | Description            | Mechanic | Total |
| SWAY  | SWAY CONTROL INSTALLED | GAH      | N/C   |
| SWAY  | SWAY CONTROL INSTALLED | DGH      | N/C   |

| Parts    |                               |      |       |       |
|----------|-------------------------------|------|-------|-------|
| Part #   | Description                   | Qty  | Price | Total |
| BRV17200 | DELUXE SWAY CONTROL           | 1.00 | N/C   | N/C   |
| DRT26003 | CLSIII SWAY CONT ADAPTER      | 1.00 | N/C   | N/C   |
| 45065    | 45065 6" DROP 7.5K BALL MOUNT | 1.00 | N/C   | N/C   |
|          | W/2-5/16" BALL MOUNT          |      |       |       |

| Other Services |               |      |       |       |
|----------------|---------------|------|-------|-------|
| Code           | Description   | Qty  | Price | Total |
| SS             | SHOP SUPPLIES | 1.00 | N/C   | N/C   |

Subtotal for Job #SWAYB: 0.00

#### Job #DELUXE - Internal

COMPLAINT: DELUXE STARTER KIT

CORRECTION: PUT IN UNIT

W/O: 73649  
Promised Date: 16 MAY 24



Customer #: 54784  
BRYAN, PATRICIA



W/O: 73649  
Promised Date: 16 MAY 24



Customer #: 54784  
BRYAN, PATRICIA



### Parts

| Part # | Description        | Qty  | Price | Total |
|--------|--------------------|------|-------|-------|
| 44722  | DELUXE STARTER KIT | 1.00 | N/C   | N/C   |

**Subtotal for Job #DELUXE: 0.00**

### Job #MONSTER - Internal

COMPLAINT: MONSTER SEAL IN ALL TIRES

CAUSE: monster seal

CORRECTION: jacked up each tire and let out air and pumped in monster seal and aired back up and spun tires.

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | N/C   |

**Subtotal for Job #MONSTER: 0.00**

### Job #1 - Warranty

COMPLAINT: THE ROD ON THE RIGHT REAR SCISSOR JACK IS BENT

CAUSE: right rear jack

CORRECTION: filled out sheet to order jack, we had one, so when new one comes in put in stock for parts, took off old jack and installed new jack. tagged old jack and put in back room.

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | DGH      | 42.50 |

### Parts

| Part #    | Description                             | Qty  | Price | Total |
|-----------|-----------------------------------------|------|-------|-------|
| C01283376 | JACK, SCISSOR BEARCLAW 24"<br>5000# W/S | 1.00 | 28.93 | 28.93 |

**Subtotal for Job #1: 71.43**

Parts Total: 28.93  
Labour Total: 42.50  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 71.43**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 24 May 2024

