



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73651
Promised Date:
24 MAY 24

CUSTOMER WORK ORDER

WO #: 73651

Customer: 28394 - ROOT, KENNETH -
270-339-7134

Tag:

Author: BH

Location: 0710 CHECK WORK

Stock #: 11314

Stock Desc: 2024 TT COACHMEN

CATALINA 333FKTSLE

Chassis #: 5ZT2CAYB3RX030592

Serial #: 5ZT2CAYB3RX030592

Mileage: 0

Licence:

Invoice #:

Date In: 13 MAY 24

Promised: 31 MAY 24

Date Sched:

Completed: 10 JUL 24

Warr. Date: 14 MAY 24

Job #51-1722 - Warranty

51-1722 RECALL FOR ROOF MOUNT SOLAR INLET

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	85.00

Parts

Part #	Description	Qty	Price	Total
69-8349	N102101T SELF-LEVELING SEALER - ALPHA SYSTEM	1.00	8.08	8.08

Subtotal for Job #51-1722: 93.08

Job #1 - Internal

Scratches on front glass 4 places

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
F100330110	WINDOW CURVED 59.812 X 21.750 RM TBH UNIV VERTICAL CONTOUR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
FRT	FREIGHT-WINDOW AND METAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

The hole for the Manuel over ride for
slide room is not where they drilled for

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	340.00

Parts

Part #	Description	Qty	Price	Total
C01307180	METAL, .040 14 X 168 3" RAD D-2 H MA	1.00	146.92	146.92



Customer #: 28394
ROOT, KENNETH



Subtotal for Job #2: 486.92

Job #3 - Warranty

The hole for the spare on the bottom metal is in the wrong location

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	255.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	28.90
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	56.10

Parts

Part #	Description	Qty	Price	Total
C01307180	METAL, .040 14 X 168 3" RAD D-2 H MA	1.00	146.92	146.92

Subtotal for Job #3: 486.92

Job #5 - Internal

COMPLAINT: Big gap of silicone on the inside of awning fabric about middle

CAUSE: something on awning

CORRECTION: got ladder and checked in middle of awning and it was just loose awning material, and helped ben measure mwtal and front cap window.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #5: 0.00

Job #4 - Internal

THE FRONT VALANCE AND BLIND WILL NOT STAY UP

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Subtotal for Job #4: 0.00

Job #6 - Internal

TRIM LAYING INSIDE NEED IT REMOVED

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Subtotal for Job #6: 0.00

Parts Total: 301.92
 Labour Total: 765.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 1,066.92

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer Signature : _____

Date: 10 Jul 2024

W/O: 73651
Promised Date: 31 MAY 24



Customer #: 28394
ROOT, KENNETH



Customer Order

