



Warranty Authorization Form

Date: 7/15/2024

Basden RV Center, Inc. DBA/
American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 66925

Unit: 7M5TD2929RC303528

Series: Delta

Model: 2024DEL262RB

Notes: NEW AUTH: 7/2: Dayra - Vendor approved (R&R of the REFER FCR10DCGTA-KL.) – “We will approve pre approve up to 1.5 for labor. Please note: Your coach information AND/OR test results will need to satisfy the conditions for Warranty credit. Return parts authorization does not guarantee your claim will be paid. Mobile fees are not covered under the Lippert warranty for this product. Please provide pictures of the complete serial number tag with your claim submission as this product is not required to be returned for testing. This is pre-auth for the R&R of the REFER FCR10DCGTA-KL. ” - attached 7/2: Dayra - Sent New Info to the Vendor awaiting response. 6/18: Dayra - Sent to the Vendor awaiting response.

Status: Approved with Modifications

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman

Return Fax #:

Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 20038 SPRAY PORT - REPLACE (part return in Fault Code: VENDOR US)

Serial #:

Model #:

Notes:

Problem: OUTDOOR SHOWER IN LEFT SIDE OF PASS THUR CHECK VALVE NOT WORKING

Time Requested: .4

Cause: Outdoor shower in left side pass thru check valve not working

Time Allowed: .2

Remedy: Remove and replace shower/spray port with new port. Test ok

Sublet Repairs: 0.00

Part Return Req: Yes

Status: Approved with Modifications

Operation Line 2

Flat Rate Code: 20034 SHOWER SURROUND - RESEAL Fault Code: GAPS / VOIDS

Serial #:

Model #:

Notes:

Problem: SHOWER SURROUND NEEDS SEALED AT THE TOP

Time Requested: .4

Cause: Shower surround needs sealed

Time Allowed: .3

Remedy: Seal shower surround at top

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved with Modifications

Operation Line 3

Flat Rate Code: 14055 FIRE EXTINGUISHER - HARDWARE - *Fault Code:* LOOSE
REPLACE

Serial #: *Model #:* *Notes:*

Problem: FIRE EXTINGUISHER PULLED OFF THE WALL

Time Requested: .2

Cause: Fire extinguisher pulled off the wall

Time Allowed: .1

Remedy: Reattach fire extinguisher bracket to the wall.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved with Modifications

Operation Line 4

Flat Rate Code: 22541 REFRIGERATOR - FURRIOR - COMPLETE REPLACE *Fault Code:* VENDOR
(model/serial # required)(Photos required)(Furrion auth required)

Serial #: na *Model #:* fcr10dcgta *Notes:* 7/2: Dayra - Vendor approved (R&R of the REFER FCR10DCGTA-KL.) – “We will approve pre approve up to 1.5 for labor. Please note: Your coach information AND/OR test results will need to satisfy the conditions for Warranty credit. Return parts authorization does not guarantee your claim will be paid. Mobile fees are not covered under the Lippert warranty for this product. Please provide pictures of the complete serial number tag with your claim submission as this product is not required to be returned for testing. This is pre-auth for the R&R of the REFER FCR10DCGTA-KL. ” - attached 7/2: Dayra - Sent New Info to the Vendor awaiting response. 6/20: Dayra - Vendor approved (R&R of the C-FCR10DCGTA-007 spark-free Thermostat (temperature controller) .) – “We will approve up to .3 for labor. Please note: Your coach information AND/OR test results will need to satisfy the conditions for Warranty credit. Return parts authorization does not guarantee your claim will be paid. Mobile fees are not covered under the Lippert warranty for this product. Please provide pictures of the complete serial number tag with your claim submission as this product is not required to be returned for testing. This is pre-auth for the R&R of the C-FCR10DCGTA-007 spark-free Thermostat (temperature controller) . ” - attached 6/18: Dayra - Sent to the Vendor awaiting response. /18 Harlie: A photo of the serial# tag is required. This is located inside the doors on the bottom 0618 BEN: Photo has been added thank you

Problem: FRIDGE DOES NOT COOL INSIDE

Time Requested: 1.8

Cause: Fridge doesn't work

Time Allowed: 1.8

Remedy: Remove and tested according to furrion specs. Fridge needs replaced Reinstall fridge to close the slide

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved with Modifications