



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73654
Promised Date:
24 MAY 24

CUSTOMER WORK ORDER

WO #: 73654

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag: BH - PARTS ORDERED. 6-24-24
Author: PH
Location: 0715 check work

Stock #: 11390
Stock Desc: 2024 TT ALLIANCE RV
DELTA 262RB
Chassis #: 7M5TD2929RC303528
Serial #: 7M5TD2929RC303528
Mileage: 0
Licence:

Invoice #:
Date In: 13 MAY 24
Promised: 31 MAY 24
Date Sched:
Completed: 15 JUL 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*74157 on 08 JUL 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: PDI new trailer

CORRECTION: Checked
Water and plumbing systems
Electrical system
12vdc system
LP system, passed leak test
Interior and exterior
Lights
Running gear
Left front shower in passed thru leaks
Shower needs sealed
Fire extinguisher pulled out of the wall
Reefer doesn't cool

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: OUTDOOR SHOWER IN LEFT SIDE OF PASS THUR CHECK VALVE NOT WORKING

CAUSE: Outdoor shower in left side pass thru check valve not working

CORRECTION: Remove and replace shower/spray port with new port. Test ok

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	34.00



Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 73654
Promised Date: 31 MAY 24

Customer #: 1000
BASDEN'S AMERICAN RV,

Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00

Parts

Part #	Description	Qty	Price	Total
10385	10385 - COILED HOSE W/METAL Q.C.	1.00	N/C	N/C
24404	Spray Port - O/S w/Metal MPT Connect	1.00	11.99	11.99

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SPRAY PORT	1.00	11.45	11.45
FRT	UPS-T-STAT CONTROLLER	1.00	10.49	10.49

Subtotal for Job #1: 67.93

Job #2 - Warranty

COMPLAINT: SHOWER SURROUND NEEDS SEALED AT THE TOP

CAUSE: Shower surround needs sealed

CORRECTION: Seal shower surround at top

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	51.00

Subtotal for Job #2: 51.00

Job #3 - Warranty

COMPLAINT: FIRE EXTINGUISHER PULLED OF THE WALL

CAUSE: Fire extinguisher pulled off the wall

CORRECTION: Reattach fire extinguisher bracket to the wall.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	17.00

Subtotal for Job #3: 17.00

Job #4 - Warranty

COMPLAINT: FRIDGE DOES NOT COOL INSIDE

CAUSE: Fridge doesn't work

CORRECTION: Remove and tested according to furrion specs. Fridge needs replaced

Reinstall fridge to close the slide

Replaced thermostat, reefer still doesn't cool

Furrion tech support had advised to replace reefer.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	51.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	170.00

Parts

Part #	Description	Qty	Price	Total
27106	27106 Thermostat - Temperature Contr	1.00	19.99	19.99
21318	10cuft - 12v - RH - w/Glass Doors -	1.00	749.99	749.99



Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT-REFER	1.00	112.26	112.26

Subtotal for Job #4: 1,188.24

Job #5 - Warranty

COMPLAINT: THE REFRIGERATOR THERMOSTAT NEEDS TO BE REPLACED

CAUSE: Replace thermostat

CORRECTION: Replaced thermostat, reefer still doesn't cool
Furrion tech support had advised to replace reefer.

Subtotal for Job #5: 0.00

Parts Total: 781.97
Labour Total: 408.00
Sublet Total: 0.00
Extras Total: 134.20
WORK ORDER TOTAL: 1,324.17

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Jul 2024

W/O: 73654
Promised Date: 31 MAY 24



Customer #: 1000
BASDENS AMERICAN RV,

