

aim Response

5/22/2024
03:17:10 pm

aim: C3634458

Non-Warranty Goodwill Adjustment

Last Modified by: ambri

Item	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed Type	Date of Purchase
------	---------------	-------------------	-------------	-----	----------	--------	-----------------------	------------	--------------	------------------

634458	73707	5/17/2024	5/17/2024	4YDT26224K3100917		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	170.00	0.00	SA21-414 7/29/20
--------	-------	-----------	-----------	-------------------	--	------	---	--------	------	------------------

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
		1.00	0.00	0.00	15.00	0.00	0.00	0.00	0.00	Approved

rs hall in unit

Operation	Description	Svc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442K	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION: 71 COMPONENT: 414 OPERATION: 7141442B Cause: Lp regulator in recall is not on camper Correction: Camper has had the lp regulator changed at one time		0.30	0.30	51.00	0.00	1	0.30	Approved

Submitted parts & sublet	0.00	Approved parts & sublet	0.00
Submitted labor & sublet	51.00	Approved labor & sublet	51.00
Submitted freight:	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	51.00	Total approved:	51.00