



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73743
Promised Date:
24 MAY 24

CUSTOMER WORK ORDER

WO #: 73743 (Appointment Date: 22 MAY 2024 - Time: 10:00am)

Customer: 53911 - WAHNSIEDLER,
JAMES T. - 812-598-9696

Stock #: 11173

Stock Desc: 2024 TT COACHMEN
CATALINA SUMMIT SERIES 164BHX

Invoice #:

Date In: 22 MAY 24

Promised: 31 MAY 24

Date Sched:

Completed: 30 JUN 24

Warr. Date: 08 SEP 23

Tag:

Author: BJW

Location: 0701 BJ TO TALK TO BH TO

SEE IF CUSTOMER'S UNIT IS ALREADY

REPAIRED

Chassis #: 5ZT2CAEC9RK006713

Serial #: 5ZT2CAEC9RK006713

Mileage: 0

Licence:



Job #1 - Warranty

COMPLAINT: 51-1722 ROOF MOUNT SOLAR INLET

CAUSE: 51-1722 ROOF MOUNT SOLAR INLET

CORRECTION: Took pictures before replacement. 5/24/24: Turned in parts request for replacement part.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00

Parts

Part #	Description	Qty	Price	Total
F100530500	CABLE ENTRY ROOF PLATE FOR SOLAR SYS	1.00	9.49	9.49

Subtotal for Job #1: 94.49

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE REGRIGERATOR LIGHT COMES ON, BUT THE REFRIGERATOR IS NOT COOLING. CUSTOMER WANTS TO KNOW IF WE CAN SWITCH DOOR TO OPEN OTHER DIRECTION

CAUSE: CUSTOMER ADVISES THAT THE REFRIGERATOR LIGHT COMES ON, BUT THE REFRIGERATOR IS NOT COOLING

CORRECTION: Turned refrigerator on at 3:45 pm, 5/24/24 to see if it starts to cool down. Did not start to cool down. Removed cabinet and pulled refrigerator out of cabinet. Disconnected power wires and placed unit on shop floor.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	51.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



Customer #: 53911
WAHNSIEDLER, JAMES T.



F100463470 REFER, 3.3 CU FT 12V BLACK IRV LH 1.00 376.66 376.66
iR

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
Subtotal for Job #2:				427.66

Job #3 - Warranty

COMPLAINT: 24V254,2024-214 CHARGE LINE OVERCURRENT PROTECTION

CAUSE: 24V, 2024-214 CHARGE LINE OVERCURRENT PROTECTION.

CORRECTION: Removed terminal nuts and moved the Distribution wire to the protected side of battery. Tightened nut securely. Resprayed terminals with protectant.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00
Subtotal for Job #3:			34.00

Job #4 - Warranty

COMPLAINT: THE VENT COVER FOR THE STOVE VENT IS MISSING.

CAUSE: THE VENT COVER FOR THE STOVE VENT IS MISSING

CORRECTION: Moved unit into shop from service lot. Checked stove vent. outside cover missing. Complete outside stove vent must be replaced. 5/24/24: Turned in parts request for a matching replacement.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	51.00

Parts

Part #	Description	Qty	Price	Total
C01237510	VENT, ENDURA RANGE VENT ASSY, 1-1/2"	1.00	8.11	8.11

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-VENT	1.00	17.30	17.30
Subtotal for Job #4:				76.41

Parts Total: 394.26
Labour Total: 221.00
Sublet Total: 0.00
Extras Total: 17.30
WORK ORDER TOTAL: 632.56

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Jul 2024



W/O: 73743
Promised Date: 31 MAY 24



Customer #: 53911
WAHNSIEDLER, JAMES T.

