

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73763
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11398 - 2024 MONTANA 3531RE 4YDFM0S21R4701193
VIN: 4YDFM0S21R4701193 HIN: SER#: 4YDFM0S21R4701193
Mileage: 0 Work Order Comp: 31 MAY 24
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 24 MAY 24 Inv #: 405505

WO # Job # Description JOB INFORMATION

73763 6 BLIND ADJUSTMENT ROD MISSING AT WINDOW BEHIND RANGE
BLIND ADJUSTMENT ROD MISSING AT WINDOW BEHIND RANGE.
Replaced missing adjustment rod at window behind Range.
73763 4 END MISSING ON LEFT DAY/NIGHT SHADE BY KITCHEN SINK
END CAP MISSING ON LEFT DAY/NIGHT SHADE BY KITCHEN SINK.
Took picture of end of roll up shade where cap is missing.
5/31/24: Turned in parts request for replacement end cap.
73763 2 CORNER TRIM NEXT TO CONTROL PANEL HAS NAILS STICKING OUT
CORNER TRIM NEXT TO CONTROL PANEL HAS NAILS STICKING OUT
Counter sunk nails and filled all holes around them with matching
putty
73763 3 SCREEN DOOR HITS DOOR FRAME
SCREEN DOOR HITS DOOR FRAME (NOTED AT DELIVERY)
Adjusted screen door latch mounted on entrance door frame.
73763 5 LIVING ROOM TV WILL NOT LIFT OUT OF CABINET
LIVING ROOM TV WILL NOT LIFT OUT OF CABINET
Lift cable off of pulley. Lifted TV manually and put cable back
on pulley. TV is sitting crooked on lift frame. Removed
fireplace for access to tv lift mounting screws. Only one
mounting screw securing lift to rear wall. Replaced missing
mounting screw. Checked operation of tv lift. Now operating as
it should. Remounted fireplace.

Claim : 73763

 WO # Job # Description JOB INFORMATION

73763 7 WINDOW BEHIND COUCH NOT CONNECTED TO KNOB
 WINDOW BEHIND COUCH NOT CONNECTED TO KNOB
 Removed window screen. Drilled out rivets holding crank to
 window frame. Straightened crank arms. inserted roller ends of
 arms into window track. Installed new rivets to secure crank
 to window frame. Checked operation of remounted window crank.
 OK. Reinstalled window screen.

73763 8 THE BATHROOM CABINET PANEL IS LOOSE.
 BATHROOM CABINET PANEL LOOSE.
 Panel on left side of cabinet over bathroom sink is loose.
 Factory staples did not catch frame behind panel. Reattached
 panel at bottom and top. Filled all holes with matching putty.

Part No	Job#	Description	PARTS	Qty	Price	Total
RVDA303	6	A303 MINI BLIND WAND		1.00	3.35	3.35
588321	4	SHADE - END CAP - FOR ROLLER SHAD		1.00	0.77	0.77

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	6	MISCELLANEOUS REPAIR		0.10	170.00	17.00
Z990	4	MISCELLANEOUS REPAIR		0.00	170.00	0.00
Z990	4	MISCELLANEOUS REPAIR		0.10	170.00	17.00
Z990	2	MISCELLANEOUS REPAIR		0.10	170.00	17.00
Z990	3	MISCELLANEOUS REPAIR		0.20	170.00	34.00
Z990	5	MISCELLANEOUS REPAIR		0.40	170.00	68.00
Z990	5	MISCELLANEOUS REPAIR		0.00	170.00	0.00
Z990	7	MISCELLANEOUS REPAIR		0.10	170.00	17.00
Z990	8	MISCELLANEOUS REPAIR		0.20	170.00	34.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	4	UPS-END CAP		1.00	17.89	17.89

Parts Total: 4.12
 Labour Total: 204.00
 Sublet Total: 0.00
 Extras Total: 17.89

>>>> Claim Total: 226.01

Customer Signature: _____

Date: _____