

# e-Authorization

6/7/20  
03:47:40

Authorization number PA03680419 Reference no: 73763 Status: Approved Approved by perrg Approved date 6/6/2024  
 Technician Name Address Address VIN Retail sold on

94 Basden's American RV Basden's American RV 4YDFM0S21R4701193  
 600 E Baseline Rd  
 Evansville, IN 47725

Job #	Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3201814A	Decorative Wood	0.00	0.20	0.10		1	0.10	Complaint: CORNER TRIM NEXT TO CONTROL PANEL HAS NAILS STICKING OUT Cause: CORNER TRIM NEXT TO CONTROL PANEL HAS NAILS STICKING OUT Correction: Counter sunk nails and filled all holes around them with matching putty
2	2300814F	Entrance Door - I-	0.00	0.20	0.20		1	0.20	Complaint: SCREEN DOOR HITS DOOR FRAME Cause: SCREEN DOOR HITS DOOR FRAME (NOTED AT DELIVERY) Correction: Adjusted screen door latch mounted on entrance door frame.
3	3304524F	Shade - Pleated -	0.00	0.10	0.10		1	0.10	Complaint: END MISSING ON LEFT DAY/NIGHT SHADE BY KITCHEN SINK Cause: END CAP MISSING ON LEFT DAY/NIGHT SHADE BY KITCHEN SINK. Correction: Took picture of end of roll up shade where cap is missing. 5/31/24: Turned in parts request for replacement end cap.
4	4209314A	TV Lift Mechanism	0.00	0.80	0.40		1	0.20	Complaint: LIVING ROOM TV WILL NOT LIFT OUT OF CABINET Cause: LIVING ROOM TV WILL NOT LIFT OUT OF CABINET Correction: Lift cable off of pulley. Lifted TV manually and put cable back on pulley. TV is sitting crooked on lift frame. Removed fireplace for access to tv lift mounting screws. Only one mounting screw securing lift to rear wall. Replaced missing mounting screw. Checked operation of tv lift. Now operating as it should. Remounted fireplace.
5	2315614A	Window - 47" or L	0.00	0.10	0.10		1	0.10	Complaint: BLIND ADJUSTMENT ROD MISSING AT WINDOW BEHIND RANGE Cause: BLIND ADJUSTMENT ROD MISSING AT WINDOW BEHIND RANGE. Correction: Replaced missing adjustment rod at window behind Range.

For paper claims only, use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

**e-Authorization**

Job Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
6 2315624B	Window - 47" or L	0.00	0.10	0.10		1	0.10	Complaint:WINDOW BEHIND COUCH NOT CONNECTED TO KNOB Cause:WINDOW BEHIND COUCH NOT CONNECTED TO KNOB Correction:Removed window screen. Drilled out rivets holding crank to window frame. Straightened crank arms. Inserted roller ends of arms into window track. Installed new rivets to secure crank to window frame. Checked operation of remounted window crank. OK. Reinstalled window screen.
7 3100814A	Cabinet Door - Re	0.00	0.20	0.20		1	0.20	Complaint:THE BATHROOM CABINET PANEL IS LOOSE. Cause:BATHROOM CABINET PANEL LOOSE. Correction:Panel on left side of cabinet over bathroom sink is loose. Factory staples did not catch frane behind panel. Reattached panel at bottom and top. Filled all holes with matching putty.
3-Authorization number PA03680419				<u>1.20</u>				

For paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the