

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73795
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 54800 - DANIEL RAMIREZ
Address: 3302 HARDWOOD FOREST DR LOUISVILLE, KY

40214

Phone: 956-422-0047

Stock Number: 11384 - 2024 SPRINGDALE 310BR 4YDTSGR21R7104499

VIN: 4YDTSGR21R7104499 HIN: SER#: 4YDTSGR21R7104499

Mileage: 0

Work Order Comp: 14 JUN 24

Auth. No:

Dealer #: 1194

Warr. Date: 31 MAY 24

Work Order Date: 29 MAY 24

Inv #: 405755

WO # Job # Description JOB INFORMATION

73795 1 NO TV RECEPTION IN REAR BEDROOM

NO TV RECEPTION IN REAR BEDROOM

Connected test TV to antenna connection in rear bedroom. No TV signal. Removed antenna connector from under bunk mounting. Connector would not pull out far enough to check connections. Removed bunk mattress and mattress board. Found coax cables pinched between bed frame and board. Cutout pinched areas and replaced coax ends. Checked for TV signal. Still no TV signal. Removed TV booster from wall and front bedroom cable connections. Checked all cables to see if connected correctly. All cables checked OK. Installed a test splitter at rear coax connections. Rear bedroom TV locations now receives TV signal. Removed test cable splitter and installed new splitter. TV signal is OKI at rear bedroom location. Remounted TV connections at all locations. Rchecked TV signal at all locations, inside and outside.

Part No Job# Description PARTS Qty Price Total

532542 1 COAX SPLITTER 1.00 8.27 8.27

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISCELLANEOUS REPAIR 0.00 170.00 0.00

Z990 1 MISCELLANEOUS REPAIR 1.50 170.00 255.00

Claim : 73795

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****

```

```

Parts Total:      8.27
Labour Total:    255.00
Sublet Total:     0.00
Extras Total:     0.00
>>>> Claim Total: 263.27

```

Customer Signature: _____

Date: _____