

Pre-Authorization

Pre-Authorization number PA03679720 Reference no: 73795 Status: Approved Approved by blaci Approved date 6/10/2024
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGR21R7104499 5/31/2024
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5101206A	Coax, TV - Repair	0.00	1.50	1.50		1	0.30	Complaint:NO TV RECEPTION IN REAR BEDROOM Cause:NO TV RECEPTION IN REAR BEDROOM Correction:Connected test TV to antenna connection in rear bedroom. No TV signal. Removed antenna connector from under bunk mounting. Connector would not pull out far enough to check connections. Removed bunk mattress and mattress board. Found coax cables pinched between bed frame and board. Cutout pinched areas and replaced coax ends. Checked for TV signal. Still no TV signal. Removed TV booster from wall and front bedroom cable connections. Checked all cables to see if connected correctly. All cables checked OK. Installed a test splitter at rear coax connections. Rear bedroom TV locations now receives TV signal. Removed test cable splitter and installed new splitter. TV signal is OKI at rear bedroom location. Remounted TV connections at all locations. REchecked TV signal at all locations, inside and outside.

Pre-Authorization number PA03679720 1.50

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company