

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73821
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 53344 - SHERRI A. BEASLEY
Address: 1102 W TENNESSEE ST EVANSVILLE, IN

47710

Phone: 812-204-3820

Stock Number: 11010 - 2023 CHEROKEE 274WK 4X4TCKC25PX161419

VIN: 4X4TCKC25PX161419 HIN:

SER#: 4X4TCKC25PX161419

Mileage: 0

Work Order Comp: 31 MAY 24

Auth. No:

Dealer #:

Warr. Date: 16 FEB 24

Work Order Date: 31 MAY 24

Inv #: 405477

WO # Job # Description JOB INFORMATION

73821 1 CUSTOMER HAS BEEN NOTICING WATER RUNNING OUT IN THE BATHROOM
FLOOR WHEN SHE TAKES A SHOWER.
shower is leaking
ran water in shower and it was coming out of frame and under
frame and underneath shower, found where screw was shot through
frame and not sealed up, went inside shower and ran fan to dry
everything and took out all silicone, resiliconed inside shower
and outside and frame where glass hits frame, then siliconed
screw, will let dry to test again. water tested shower and no
leaks.

73821 2 DURING ONE OF THE RECENT HARD RAINS, CUSTOMER NOTICED WATER IN
THE BATHROOM FLOOR AND IT WAS RUNNING TOWARDS THE CABINETS.
CUSTOMER WANTS TO BE SURE THAT WATER DOESN'T DAMAGE CABINETS.
after hard rain water in bathroom floor
looked outside and found several gaps in sealer around outside
shower and on the outside wall, siliconed all gaps where water was
coming in and found hot side under sink was leaking going to
floor and coming out under cabinet, took off hot line and replace
cone washer and rehooked and tested and no more leaks.

73821 4 CUSTOMER NOTICED WATER IN THE FLOOR UNDER THE EMERGENCY WINDOW
AFTER ONE OF THE HARD RAINS THAT WE RECENTLY HAD.
water on floor under emergency window in last rain
checked window on outside and sealed window, sealer was cracked
open, when it dries i will run water over it to make sure. ran

Claim : 73821

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

water over outside window and no more leaks.also it could of been
the line under the sink going under wall to bedroom getting water
in there.,

Part No	Job#	Description	PARTS	Qty	Price	Total
---------	------	-------------	-------	-----	-------	-------

ESC06435	1	CONE WASHER SWIVEL SEAL		2.00	0.26	0.52
----------	---	-------------------------	--	------	------	------

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
----------	------	-------------	--------	-----	------	-------

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.07	170.00	11.90
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.13	170.00	22.10
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.02	170.00	3.40
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.14	170.00	23.80
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.04	170.00	6.80

Parts Total:	0.52
Labour Total:	153.00
Sublet Total:	0.00
Extras Total:	0.00

>>>> Claim Total: 153.52

Customer Signature: _____

Date: _____