

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1944091
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKC25PX161419
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT274WK
SHERRI A BEASLEY		DEALER RO #	73821
1102 W TENNESSEE ST		CLAIM START DATE	06/06/2024
Evansville, IN 47710		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	03/09/2024	WARRANTY EXPIRATION DATE	03/09/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-141-12-00-001592	Tub Surround to Wall, each section - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-06-06 15:22:43 :: CUSTOMER HAS BEEN NOTICING WATER RUNNING OUT IN THE BATHROOM FLOOR WHEN SHE TAKES A SHOWER. shower is leaking ran water in shower and it was coming out of frame and under frame and underneath shower, found where screw was shot through frame and not sealed up, went inside shower and ran fan to dry everything and took out all silicone, resiliconed inside shower and outside and frame where glass hits frame, then siliconed screw, will let dry to test again. water tested shower and no leaks.			
Model#		Dlr Sub Hrs	1.20	Sub Labor Amt \$204.00
Serial#		Appr Hrs	0.50	Appr Labor Amt \$85.00
	Notes			
	sealed			
	thank you			

Labor

Line# 2	Operation Code	Operational Description		
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-06-06 15:28:03 :: DURING ONE OF THE RECENT HARD RAINS, CUSTOMER NOTICED WATER IN THE BATHROOM FLOOR AND IT WAS RUNNING TOWARDS THE CABINETS. CUSTOMER WANTS TO BE SURE THAT WATER DOESN'T DAMAGE CABINETS. after hard rain water in bathroom floor looked outside and found several gaps in sealer around outside shower and on the outside wall, siliconed all gaps where water was coming in and found hot side under sink was leaking going to floor and coming out under cabinet, took off hot line and replace cone washer and rehooked and tested and no more leaks.			
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$34.00
	Notes			
	repaired/sealed			

Labor

Line# 3	Operation Code	Operational Description		
	20-46-19-00-000721	Window - Exterior/Windows/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-06-06 15:28:50 :: CUSTOMER NOTICED WATER IN THE FLOOR UNDER THE EMERGENCY WINDOW AFTER ONE OF THE HARD RAINS THAT WE RECENTLY HAD.. water on floor under emergency window in last rain checked window on outside and sealed window, sealer was cracked open, when it dries i will run water over it to make sure. ran water over outside window and no more leaks. also it could of been the line under the sink going under wall to bedroom getting water in there.,			

Model#

Dlr Sub Hrs 0.20

Sub Labor Amt \$34.00

Serial#

Appr Hrs 0.20

Appr Labor Amt \$34.00

Notes

Submitted

Labor Amt	\$272.00
Parts & Freight	\$0.00
Total	\$272.00

Approved

Labor Amt	\$153.00
Parts & Freight	\$0.00
Total	\$153.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.