

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73832
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11406 - 2024 CATALINA SUMMIT SERIES 164BHX 5ZT2CAEC3RK008232
VIN: 5ZT2CAEC3RK008232 HIN: SER#: 5ZT2CAEC3RK008232
Mileage: 0 Work Order Comp: 16 JUL 24
Auth. No: Dealer #:
Warr. Date: Work Order Date: 03 JUN 24 Inv #: 407106

WO # Job # Description JOB INFORMATION

73832 1 BACKWALL HAS A DENT UNDER WWW.COACHMAN.COM DECAL
Dent in the back wall
Received the new panel and unboxed. Unscrewed the taillights, city
water connection and black tank flush connection. Pulled off the
vinyl inserts then unscrewed the corner trim. Started at the
bottom panel by removing the staples then removed the staples
from the next to up. Set the panels to the side the measured and
cut the new panel to length. Set new panel in place and stapled
and same for the next to panels. Put the taillights, city water
connection and black tank flush connection back on. Put the
corner trim back on followed by the vinyl insert. Trimmed around
the taillights, corner trim, city water connection and black tank
flush connection with the silver silicone. Cleaned the panel
surface then applied the coachmen decal.
73832 2 BATHROOM DOOR HAS A SMALL SCRATCH
Bathroom door has scratches on it
Use fil sticks to fill scratches and blend in to match the door
73832 3 ALL OUTLETS TESTING POWER TO GROUND
Outlets testpower to ground
Living room outlet had bad connections, pull all outlets out and
check wiring. Living room wires were loose, reattach wires and
all are working right. Reinstall all outlets.
73832 4 HAVE A LOOSE CONNECTION BEHIND THE CONVERTER

Claim : 73832

 WO # Job # Description JOB INFORMATION

Loose connection behind converter, bad chassis ground
 Found chassis grounds on the frame. Repaired chassis grounds.
 The interior lights no longer flicker as the chassis flexes.

 Part No Job# Description PARTS Qty Price Total

 1099150 1 DECAL, WEB SITE BLACK WWW.COACHME 1.00 2.43 2.43
 C01303901 1 METAL, .024 X 16" X 96" 1MDM SL C 1.00 52.27 52.27

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 3.00 170.00 510.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 1.00 170.00 170.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.10 170.00 17.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 1.00 20.00 20.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.87 170.00 147.90
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.13 170.00 22.10
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.50 170.00 255.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.50 170.00 85.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS-DECAL 1.00 17.29 17.29
 FRT 1 FREIGHT-METAL 1.00 368.17 368.17

Parts Total: 54.70
 Labour Total: 1,227.00
 Sublet Total: 0.00
 Extras Total: 385.46

>>>> Claim Total: 1,667.16

Customer Signature: _____

Date: _____