



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73832
Promised Date:
24 JUL 24

CUSTOMER WORK ORDER

WO #: 73832

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag: PH - PARTS ORDERED 6-14-24
Author: PH
Location: 0718 SEE IF CAM GOT
INVOICE YET

Stock #: 11406
Stock Desc: 2024 TT COACHMEN
CATALINA SUMMIT SERIES 164BHX
Chassis #: 5ZT2CAEC3RK008232
Serial #: 5ZT2CAEC3RK008232
Mileage: 0
Licence:

Invoice #:
Date In: 03 JUN 24
Promised: 31 JUL 24
Date Sched:
Completed: 16 JUL 24
Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 3 HR PDI

CAUSE: PDI new trailer

CORRECTION: Checked
Water and plumbing systems
Electrical system
12vdc system
LP system
Interior and exterior
Lights
Running gear
Passed LP leak test
All tires 65 psi

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: BACKWALL HAS A DENT UNDER WWW.COACHMAN.COM DECAL

CAUSE: Dent in the back wall

CORRECTION: Received the new panel and unboxed. Unscrewed the taillights, city water connection and black tank flush connection. Pulled off the vinyl inserts then unscrewed the corner trim. Started at the bottom panel by removing the staples then removed the staples from the next to up. Set the panels to the side the measured and cut the new panel to length. Set new panel in place and stapled and same for the next to panels. Put the taillights, city water connection and black tank flush connection back on. Put the corner trim back on followed by the vinyl insert. Trimmed around the taillights, corner trim, city water connection and black tank flush connection with the silver silicone. Cleaned the panel surface then applied the coachmen decal.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 1000
BASDEN'S AMERICAN RV,



Z990	MISC LABOUR CODE (EXTERNAL)	SAR	510.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	170.00

Parts

Part #	Description	Qty	Price	Total
1099150	DECAL, WEB SITE BLACK WWW.COACHMENRV.COM	1.00	2.43	2.43
C01303901	METAL, .024 X 16" X 96" 1MDM SL COAC	1.00	52.27	52.27

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECAL	1.00	17.29	17.29
FRT	FREIGHT-METAL	1.00	368.17	368.17

Subtotal for Job #1: 1,120.16

Job #2 - Warranty

COMPLAINT: BATHROOM DOOR HAS A SMALL SCRATCH

CAUSE: Bathroom door has scratches on it

CORRECTION: Use fil sticks to fill scratches and blend in to match the door

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	17.00

Subtotal for Job #2: 17.00

Job #3 - Warranty

COMPLAINT: ALL OUTLETS TESTING POWER TO GROUND

CAUSE: Outlets testpower to ground

CORRECTION: Living room outlet had bad connections, pull all outlets out and check wiring. Living room wires were loose, reattach wires and all are working right. Reinstall all outlets.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	20.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	147.90
Z990	MISC LABOUR CODE (EXTERNAL)	JH	22.10

Subtotal for Job #3: 190.00

Job #4 - Warranty

COMPLAINT: HAVE A LOOSE CONNECTION BEHIND THE CONVERTER

CAUSE: Loose connection behind converter, bad chassis ground

CORRECTION: Found chassis grounds on the frame. Repaired chassis grounds. The interior lights no longer flicker as the chassis flexes.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	255.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	85.00

Subtotal for Job #4: 340.00



W/O: 73832
Promised Date: 31 JUL 24

Parts Total:	54.70
Labour Total:	1,227.00
Sublet Total:	0.00
Extras Total:	385.46
WORK ORDER TOTAL:	1,667.16

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Jul 2024



Customer #: 1000
BASDENS AMERICAN RV,

