



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73833



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 73833

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0628 BACKUP

Stock #: 11407
Stock Desc: 2024 TT COACHMEN
CATALINA SUMMIT SERIES 164BHX
Chassis #: 5ZT2CAEC7RK008234
Serial #: 5ZT2CAEC7RK008234
Mileage: 0
Licence:

Invoice #:
Date In: 03 JUN 24
Promised:
Date Sched:
Completed: 12 JUN 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 3 HR PDI

CAUSE: PDINTT PDI NEW TRAVEL TRAILER - 3 HR PDI

CORRECTION: Moved unit into shop from sales lot. Filled LP tanks. Installed new battery box. Checked all exterior lights and brakes. Checked lug nut and set tire pressure at 65 psi. Checked roof and awning. Checked entrance door and all compartment doors. Checked stab jacks. Checked power cord. Checked all interior lights. Checked converter output. Checked all windows and blinds. Checked all cabinets and drawers. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Replaced missing pull knobs on kitchen mini blind. Added water to fresh water tank and flushed antifreeze from water pump. Connected to city water and flushed antifreeze from all water lines and faucets. Opened by-pass on water heater and filled. Purged all air from water system. Performed LP drop test and set Lp pressure at 10.wc. Checked Refrigerator, Range, Microwave and Furnace. Checked Water Heater on LP and Electric. Checked TV Antenna at inside location with Factory supplied TV. Filled all holding tanks and checked monitor panel. Checked Radio. Drained all holding tanks, including water heater. Move unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: THERE IS NO BRAKES ON THE CURBSIDE WHEEL.

CAUSE: NO BRAKES ON CURB SIDE WHEEL

CORRECTION: Checked both wire connectors on curb side brake. One connector was not crimped all the way. crimped connector and checked brake again. Curbside brake now working.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	51.00



Subtotal for Job #1: 51.00

W/O: 73833

Parts Total: 0.00
Labour Total: 51.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 51.00

Thank you for being a valued customer. We appreciate your business.
All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 12 Jun 2024

Customer Signature : _____



Customer #: 1000
BASDENS AMERICAN RV,

