



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73914
Promised Date:
14 JUN 24

CUSTOMER WORK ORDER

WO #: 73914

Customer: 54899 - WILLIS, JONATHON
A. - 812-664-0465

Tag:

Author: BH

Location: 0708 CHECK PRE AUTH

Stock #: 11355

Stock Desc: 2024 TT COACHMEN

CATALINA 323BHDSCLE

Chassis #: 5ZT2CAXB7RX031097

Serial #: 5ZT2CAXB7RX031097

Mileage:

Licence:

Invoice #:

Date In: 10 JUN 24

Promised: 14 JUN 24

Date Sched:

Completed: 30 JUN 24

Warr. Date: 14 JUN 24

Job #FPDINTT - Internal

COMPLAINT: Transferred to BAS*74056 on 25 JUN 24

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT FINAL PDI ON NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Drilled larger holes in bottom of battery box. Installed new battery. Connected all battery cables and wires. Secured all wires together. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Checked roof and awning. Checked power cord. Checked all interior lights. Checked converter output. Checked inside and outside refrigerators. REMOVED all shipping material from all appliances. Added water to fresh water tank and flushed water pump. Connected to city water and flushed all water lines and faucets. Water heater was not drained after PDI. Flushed old water from water heater. Opened by-pass on water heater and filled. Purged all air from water system. Performed LP drop test and set LP pressure at 10 in.wc. Checked all TV antenna locations with test TV. Operated water heater on LP and Electric. Checked inside range and outside grille. Dumped all holding tanks. Water heater is full and ready to camp. Moved unit to washbay area.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER1000 - Internal

COMPLAINT: Transferred to BAS*74056 on 25 JUN 24

Estimate amount was 0.00

INSTALL 1000# EQUALIZER HITCH

CAUSE: EQUALIZ INSTALL 1000# EQUALIZER HITCH

CORRECTION: Relocated Brake-away switch on frame to clear hitch bracket. Assembled and mounted hitch brackets.

SETUP HITCH HIGHT AND HOOKED UP TO TRAILER. ADJUSTED HITCH AS NEEDED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C



Customer #: 54899
WILLIS, JONATHON A.

W/O: 73914
Promised Date: 14 JUN 24



Customer #: 54899
WILLIS, JONATHON A.



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #EQUALIZER1000:				0.00

Job #1 - Warranty

COMPLAINT: AWNING WILL NOT "POP FREE" NEEDS HELPER SPRINGS

CAUSE: AWNING WILL NOT "POP FREE" NEEDS HELPER SPRINGS

CORRECTION: Took pictures of awning in stuck position, model of awning arm and awning canvass. Installed spring kit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	51.00

Parts

Part #	Description	Qty	Price	Total
2022123083	SOLERA HELPER SPRING KIT	1.00	15.51	15.51

Subtotal for Job #1: 66.51

Job #2 - Internal

COMPLAINT: Transferred to BAS*74056 on 25 JUN 24
Estimate amount was 0.00

INSTALL CUSTOMER SUPPLIED 3 TELEVISIONS. ONE IS TO GO IN THE LIVING ROOM WITH A SWING OUT ARM. ONE IS TO GO INTO THE MAIN BEDROOM WITH A SWING OUT ARM. AND ONE IN THE BUNK HOUSE WITH A REGULAR BRACKET

CAUSE: INSTALL (3) CUSTOMER SUPPLIED TVs

CORRECTION: Moved unit back into shop to install (3) TVs. Installed breckets on all (3) Located TVs In front bdroom, Living room and rear bedroom. Mounted all (3) TVs with (2) swing outv brackets and (1) fixed bracket.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #2: 0.00

Parts Total: 15.51
Labour Total: 51.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 66.51

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 08 Jul 2024

