

e-Authorization

7/11/20
03:31:36 PM

3-Authorization number PA03686531 Reference no: 73920 Status: Approved Approved by stept Approved date 6/18/2024
receiving Name Address VIN Retail sold on

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCG123RV501808						
Item	Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base	Complaint / Cause / Correction
1	1211406B	Slide Out Mechan	0.00	7.00	5.00		1	1.50	Complaint:BEDROOM SLIDE IS CROOKED AND WONT GO IN

KRV - Please provide clear photo of the white Lippert In-Wall Slide System RPO tag (found on H Column).
KRV- Please install Part# 687936 Mechanism - Clamp Extrusion - 1/4" x 1 7/16" x 16" - Steel Strap Two each side top and bottom
The tech will need to screw the bracket into the edge of the column and then to the wall.
KRV- NOTICE***NOTICE***NOTICE***NOTICE***NOTICE
The following photos MUST be submitted with your Claim to receive payment approval.
Eight (8) photos of the In-Wall System gear rack location after completing repairs.
Note: Take measurements from the gear rack to the edge of the column with tape measurement pressed against the gear rack, not above or below. This measurement is best taken with the slide extended at 6 inches from the exterior of the coach and then again with the slide at full extension at all four corners for a total of 8 measurements.
KRV - VCB

3-Authorization number PA03686531

5.00

paper claims ~~only~~ use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the