



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73928
Promised Date: 29 JUN 24

CUSTOMER WORK ORDER

WO #: 73928

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0710 BH TO CLOSE

Stock #: 11404
Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 281RK
Chassis #: 4YDTSGN20R7105519
Serial #: 4YDTSGN20R7105519
Mileage: 0
Licence:

Invoice #:
Date In: 11 JUN 24
Promised: 29 JUN 24
Date Sched:
Completed: 10 JUL 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi new unit

CORRECTION: Ran all appliances, water lines, did lp drop test, and tested all 120 and 12 volt systems

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: BLIND OVER MICROWAVE CAME LOOSE ON ONE SIDE

CAUSE: Blind was loose

CORRECTION: I took screws out and they were all stripped so I put hole fillers in and rescrewed back on to wall

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	34.00

Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: ADJUST FRIDGE DOOR

CAUSE: Fridge would not close

CORRECTION: I lifted up fridge door and put 2 shims under the door and the door closes properly

Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 73928
Promised Date: 29 JUN 24



Customer #: 1000
BASDENS AMERICAN RV,



Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	34.00
Subtotal for Job #2:			34.00

Job #3 - Warranty

COMPLAINT: BATTEN STRIP UNDER ENTERTAINMENT CENTER IS MISSING

CAUSE: put missing batten strip up

CORRECTION: took mesuarments of entertainment center and cut pieces to match length of missing pieces i then put stripps ut and nailed in with air nailer

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	34.00

Parts Part #	Description	Qty	Price	Total
696147	Trim - Batten - 3.6mm x 1 1/2" x 96"	1.00	3.11	3.11

Other Services Code	Description	Qty	Price	Total
FRT	UPS-JOBS 3,4	1.00	80.60	80.60

Subtotal for Job #3: 117.71

Job #4 - Warranty

COMPLAINT: BATTEN STRIP IN BEDROOM IS MISSING

CAUSE: put missing batten strip up

CORRECTION: took messurments of bed room piece that was missing and cut a new piece and used air nailer to nail strip in place

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	34.00

Parts Part #	Description	Qty	Price	Total
696147	Trim - Batten - 3.6mm x 1 1/2" x 96"	1.00	3.11	3.11

Subtotal for Job #4: 37.11

Job #5 - Warranty

COMPLAINT: TRIM PIECE ABOVE BED NEEDS STAPLED BACK UP

CAUSE: Trim piece fell down

CORRECTION: I got the air stapler and regulated the air down and stapled it down

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	17.00

Subtotal for Job #5: 17.00



Parts Total: 6.22
Labour Total: 153.00
Sublet Total: 0.00
Extras Total: 80.60
WORK ORDER TOTAL: 239.82

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 10 Jul 2024

Customer Signature : _____

W/O: 73928
Promised Date: 29 JUN 24



Customer #: 1000
BASDENS AMERICAN RV,

