



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73930



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 73930

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0628 BACKUP

Stock #: 10761A
Stock Desc: 2021 TT COACHMEN
CATALINA 303QBCKLE
Chassis #: 5ZT2CAVBXMX022549
Serial #: 5ZT2CAVBXMX022549
Mileage: 0
Licence:

Invoice #:
Date In: 11 JUN 24
Promised:
Date Sched:
Completed: 19 JUN 24
Warr. Date:

Job #1 - Internal

COMPLAINT: INSPECT ROOF, FLOORS, WALLS AND SLIDE ROOMS FOR WATER DAMAGE.

CAUSE: Check walls , floors and slide room for water damage

CORRECTION: Checked floors, walls and slideroom for water damage... none found.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Subtotal for Job #1:			0.00

Job #PDIUCTT - Internal

PDI USED CERTIFIED TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C

Parts

Part #	Description	Qty	Price	Total
94196	BLK EXTERIOR SHOWER - THETFORD	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDIUCTT: 0.00

Job #BRAKE - Warranty

COMPLAINT: JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL

CAUSE: Breakaway switch wiring recall

CORRECTION: Rewired breakaway switch to hot side of battery disconnect.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	51.00

Subtotal for Job #BRAKE: 51.00

Job #2 - Internal

COMPLAINT: WALL PAPER IS PEELING IN THE CAMPER

CAUSE: Walls

CORRECTION: Heat up and glue back wall panels. Put wood tape over damaged outside in kitchen.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: BACK CABINET DOORS WON'T SHUT

CAUSE: Back bedroom cabinet doors don't close.

CORRECTION: Adjusted cabinet doors to give a gap between them enough for them to close properly.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

COMPLAINT: SCREEN DOOR NEEDS RESCREENED

CAUSE: Screen door needs rescreened

CORRECTION: Install new screen in bottom panel of screen door.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C

Subtotal for Job #4: 0.00

Job #5 - Internal

COMPLAINT: HALL LIGHTS DON'T WORK

CAUSE: Hall light doesn't work

CORRECTION: Reposition light cover over the switch to make it line up with the switch.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C

Subtotal for Job #5: 0.00

Job #6 - Internal

COMPLAINT: RIGHT TURN INOP

CAUSE: Right turn and tail light inop

W/O: 73930



Customer #: 1000
BASDEN'S AMERICAN RV,





CORRECTION: Take off cover and replace missing light bulb.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Subtotal for Job #6:			0.00

Job #7 - Internal

COMPLAINT: WATER LEAK UNDER SINK

CAUSE: Water leak under the sink

CORRECTION: Found stink bugs in check valve, cleaned out and reinstall.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Subtotal for Job #7:			0.00

Job #8 - Internal

COMPLAINT: WATER LEAK AT OUTSIDE SHOWER

CAUSE: Water leak at outdoor shower

CORRECTION: R&R outdoor shower

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Subtotal for Job #8:			0.00

Job #9 - Internal

ADD TRIM UNDER OUTSIDE REFER

Subtotal for Job #9: 0.00

Job #10 - Internal

COMPLAINT: AWNING LED LIGHTS NEED REPLACED

CAUSE: Awning LED light doesn't work

CORRECTION: R&R awning g LED lights

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C

Parts				
Part #	Description	Qty	Price	Total
6576	LED LIGHTS FOR CAREFREE AWNING- FOR	1.00	N/C	N/C

Subtotal for Job #10: 0.00



W/O: 73930

Parts Total:	0.00
Labour Total:	51.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	51.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 21 Jun 2024



Customer #: 1000
BASDEN'S AMERICAN RV,

