

Claim Response

Claim: C3660892

Non-Warranty Goodwill Adjustment

Last Modified by:stutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3660892	73952	6/13/2024	6/22/2024	4YDT20228K3106619		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	170.00	0.00	SA21-414	4/19/2019

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

5218749

Component Model: 6020

Component Serial Number: N 18 23

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B Cause: regulator recall Correction: removed old regulator and replaced with new made sure was properly secure then preformed lp safty test when doing so it was over 90 degrees and the furnace would not kick on so i had to turn on ac unit and wait for the air in the camper to get cooler while i waited i took the range top off and disconnected line going into range and hooked up to manometer when it was cool enough i was able to turn on furnace and preform lp safty test and once dropped down to 8 W.C. and waited for 5 minutes the pressure went up to 9W.C. after the five minutes (Deking/KRV)		0.50	0.50	85.00	0.00	1	0.50	Approved

Submitted parts & subLet 28.75
Submitted labor & subLet 85.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 113.75

Approved parts & subLet 28.75
Approved labor & subLet 85.00
Approved freight: 0.00
Tax: 0.00
Total approved: 113.75