

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 73993
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 53902 - PAUL B. BECKER
Address: 24 4TH ST JOHNSON CITY, NY

13790

Phone: 607-341-8744

Stock Number: 11080 - 2024 COUGAR SPORT 2100RK 4YDFCGJ27R2501234

VIN: 4YDFCGJ27R2501234 HIN:

SER#: 4YDFCGJ27R2501234

Mileage: 0

Work Order Comp: 21 AUG 24

Auth. No:

Dealer #: 1194

Warr. Date: 31 JUL 23

Work Order Date: 18 JUN 24

Inv #: 408402

WO # Job # Description JOB INFORMATION

73993 3 the catch on the cabinet is not the same color as the others in
the bed room it was missing at one time its the long cabinet door
top left
Bronze cabinet latch is missing
Inspected all the cabinets in the bedroom and found the top right
cabinet had a missing latch. Got a new latch from the parts
department. Mounted the new bronze latch and checked to make sure
the screws where tight. Couldn't find the original latch.
73993 5 THE ROOF MATERIAL ON THE SLIDE ROOM IS BUBBLING UP.TORD THE
OUTSIDE WALL TOP
FOUND THE ROOF IS BUBBLING UP
pull the old tape up and lay new down that is not bubbled
73993 6 CUSTOMER ADVISES THAT THE SPRAYER AT THE KITCHEN FAUCET LEAKS
WHEN PULLING IT OUT .
Sprayer is leaking at the top
Turned on the water pump the turned on the kitchen. Found where
the hose connection to the sprayer it is leaking water.
73993 1 THE UNDERBELLY IS FRAYING ON EACH SIDE OF THE SLIDE ROOM.
Slideroom needs skis
Ran the slideroom out and inspected the bottom of the slideroom
floor. At each end of the slideroom floor the underbelly film is
frying. Put in po sheet for slideroom skis.

Claim : 73993

WO # Job # Description JOB INFORMATION

73993 2 SHOWER NOZZLE DOES NOT STAY IN PROPER POSITION DURING TRAVEL.
SAYS IT KEEP SLIDING DOWN
Loose plumbing hardware
The shower faucet would move when turning on the water. Removed
the screws then inspected the backside of the faucet and found
the hardware was loose. Tightened all hardware then put the
screws back in and trim with silicone.

Part No Job# Description PARTS Qty Price Total

RVDH201 3 H201 ROLLER CATCH WITH PRONG 1.00 3.19 3.19
F100380780 5 J&B SLIDE SKI, 53", CURRENT 2022, 3.00 9.98 29.94
COFUBE625 5 QUICK ROOF EXTREME 6" X 25" 1.00 49.35 49.35
635088 6 Faucet - Kitchen - Pull-Out - Sin 1.00 52.34 52.34

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 3 MISCELLANEOUS REPAIR 0.10 170.00 17.00
Z990 5 MISCELLANEOUS REPAIR 0.00 170.00 0.00
Z990 5 MISCELLANEOUS REPAIR 0.00 170.00 0.00
Z990 5 MISCELLANEOUS REPAIR 1.00 170.00 170.00
Z990 6 MISCELLANEOUS REPAIR 0.09 170.00 15.30
Z990 6 MISCELLANEOUS REPAIR 0.27 170.00 45.90
Z990 6 MISCELLANEOUS REPAIR 0.14 170.00 23.80
Z990 1 MISCELLANEOUS REPAIR 0.00 170.00 0.00
Z990 1 MISCELLANEOUS REPAIR 0.30 170.00 51.00
Z990 2 MISCELLANEOUS REPAIR 0.30 170.00 51.00

Excode Job# Description EXTRAS Qty Price Total

FRT 6 UPS-FAUCET 1.00 19.40 19.40

Parts Total: 134.82
Labour Total: 374.00
Sublet Total: 0.00
Extras Total: 19.40

>>>> Claim Total: 528.22

Customer Signature: _____

Date: _____