



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73995
Promised Date:
24 JUN 24

CUSTOMER WORK ORDER

WO #: 73995

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0722 CHECK PREAUTH

Stock #: 11413
Stock Desc: 2024 TT COACHMEN
CATALINA 293QBCKLE
Chassis #: 5ZT2CAUB0RN300461
Serial #: 5ZT2CAUB0RN300461
Mileage: 0
Licence:

Invoice #:
Date In: 18 JUN 24
Promised: 31 JUL 24
Date Sched:
Completed: 19 JUL 24
Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDI new trailer

CORRECTION: Checked

Water and plumbing systems

Electrical system

12vdc system

LP system... passed leak test

Interior and exterior

Lights

Running gear

Repaired

Regulator won't adjust

Hot water heater full of antifreeze

Spray port lid won't close

Tail and marker Lights don't work... dead short.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: THE LP RUGLATOR WILL NOT ADJUST

Customer #: 1000
BASDEN'S AMERICAN RV,



CAUSE: LP REGULATOR will not adjust

CORRECTION: Replace Lp regulator with new, works correctly now.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	85.00

Parts Part #	Description	Qty	Price	Total
696405	RECALL REGULATOR KIT W/HOSES - KEYSTONE	1.00	41.99	41.99

Subtotal for Job #1: 126.99

Job #2 - Internal

COMPLAINT: SPRAY PORT LID WONT CLOSE

CAUSE: Spray port lid won't close

CORRECTION: Replace pan head screws with counter sunk screws

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JH	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: FRIPPING THE BREAKER ON THE TAIL LIGHTS

CAUSE: Tail lights tripping breaker on light tester

CORRECTION: Tail lights are tripping breaker in light tester, found top center rear marker light had a screw run through it, repaired and lights work.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	340.00

Subtotal for Job #3: 340.00

Parts Total:	41.99
Labour Total:	425.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	466.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Jul 2024

W/O: 73995
Promised Date: 31 JUL 24



Customer #: 1000
BASDEN'S AMERICAN RV,

