



Warranty Authorization Form

Date: 7/11/2024

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 68481 Unit: 7M5FP4323RB203763
Series: Paradigm Model: 2024PAR395DS
Notes:
Status: Approved

Dealer Information

American RV Basden RV Center, Inc. DBA/ American RV Requestor: Ben Hoffman
(812) 867-5200 600 E Baseline Rd Return Fax #:
Evansville, IN 47725 Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 20028 SHOWER DOORS - REPAIR (REASSEMBLE
TRAVEL LOCK OR HANDLE) - PHOTO REQUIRED

Fault Code: IMPROPERLY INSTALLED

Serial #: Model #: Notes:

Problem: IN THE BATHROOM THE HOLD BACK FOR THE SLIDING GLASS IS LAYING IN THE
SINK

Time Requested: .2

Cause: IN THE BATHROOM THE HOLD BACK FOR THE SLIDING GLASS IS LAYING IN THE
SINK.

Time Allowed: .2

Sublet Repairs: 0.00

Remedy: Set screws and rubber inserts for handles are missing. Handles need replaced.
6/21/2024: Turned in parts request for new handles and mounting parts. Parts received 6/26/2024.
Installed both shower sliding door handles on doors.

Part Return Req: No

Status: Approved

Operation Line 2

Flat Rate Code: 14085 TRIM - INTERIOR - REPAIR

Fault Code: LOOSE

Serial #: Model #: Notes:

Problem: ABOVE THE BATHROOM SINK -- BETWEEN THE MEDCABINET AND THE OTHER
CABINET THERE IS A END PANEL THAT HAS FELL DOWN AND NEEDS TO BE STAPLED
BACK UP

Time Requested: .1

Time Allowed: .1

Sublet Repairs: 0.00

Cause: ABOVE THE BATHROOM SINK -- BETWEEN THE MED CABINET AND THE OTHER
CABINET THERE IS AN END PANEL THAT HAS FELL DOWN AND NEEDS TO BE STAPLED
BACK UP

Remedy: Pushed panel back up into position. Resecured at bottom with brad nails.

Part Return Req: No

Status: Approved