



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74032

CUSTOMER WORK ORDER

WO #: 74032
Customer: 54943 - LITTLEPAGE,
DONALD - 812-204-5261
Tag:
Author: PH
Location: 0705 CHECK PREAUTH

Stock #: 11382
Stock Desc: 2024 TT COACHMEN
CATALINA 243RBSLE
Chassis #: 5ZT2CANB2RU043498
Serial #: 5ZT2CANB2RU043498
Mileage:
Licence:

Invoice #:
Date In: 24 JUN 24
Promised:
Date Sched:
Completed: 30 JUN 24
Warr. Date: 29 JUN 24

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: final pdi

CORRECTION: did final and everything on sheet,checked lp,water,electrical,and appliances,had to remove tape and foam from 2 ref,moved break away switch it was to short.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
10-7090	1pc 1/2" PLUG CAP	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: e2 hitch
INSTALLED HITCH AND SET UP TRUCK.

CORRECTION: installed brackets on tongue and put hitch stuff in side door.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #E2: 0.00



Customer #: 54943
LITTLEPAGE, DONALD



Job #DELUXE - Internal

COMPLAINT: DELUXE STARTER KIT

CORRECTION: PUT IN UNIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #BCWT - Internal

COMPLAINT: BRAKE CONTROL & WIRING - PICKUP TRUCK ONLY

CORRECTION: INSTALLED BRAKE CONTROL AND WIRING. I USED A OEM TYPE HARNESS AND TESTED THE 7-WAY OUTPUT. EVERYTHING IS WORKING AS IT SHOULD.

Labor

Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
14636	7WAY PLASTIC CAR END	1.00	N/C	N/C
19-0938	9 WAY CONNECTOR - BRACKET	1.00	N/C	N/C
19-1441	16-3030 30A CIRCUIT BREAKER	1.00	N/C	N/C
17-0081	#51120 BRAKE CONTROL	1.00	N/C	N/C
81798	81798 14-19 GM HARNESS	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BCWT: 0.00

Job #1 - Internal

COMPLAINT: INSTALL CUSTOMER SUPPLIED TV WITH ONE OF OUR SWING BRACKETS

CAUSE: install customer supplied tv

CORRECTION: took tv out of box and had to get bracket to fit tv,found bolts to bolt on bracket to tv and found screws to fit plate to wall,measured wall and tv and bracket to center tv on wall,got measurements,used wallbot to find wood in wall,then screwed mount to wall,hung tv and made coax for tv,hooked up and did channel scan,all good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
380317	Bracket - TV Swing Arm - Single - 9"	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #MONSTER - Internal

COMPLAINT: MONSTER SEAL IN ALL TIRES

CAUSE: monster seal

CORRECTION: jacked up each tire and let out air,then put monster seal in each tire,rolled tires and aired up,installed all 4 stickers.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 54943
LITTLEPAGE, DONALD



Subtotal for Job #MONSTER: 0.00

Job #2 - Internal

COMPLAINT: MAXXGARD WASH BAY

CORRECTION: HAD WASHBAY COMPLETE

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: TV BOOSTER IS BAD

CAUSE: booster fot tv is bad

CORRECTION: everytime yo move booster the light goes out and comes back on,something going on in circuit board,took old one out and had to wire in and put in place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	17.00

Parts

Part #	Description	Qty	Price	Total
555468	Antenna - Switch - Wall Plate Power	1.00	14.47	14.47

Other Services

Code	Description	Qty	Price	Total
FRT	UPS- ANTENNA BOOSTER	1.00	18.60	18.60

Subtotal for Job #3: 84.07

Job #4 - Warranty

COMPLAINT: AWNING ARMS MISSING SPRING HELPERS

CAUSE: Installed springs on awning hardware

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	51.00

Parts

Part #	Description	Qty	Price	Total
2022123083	SOLERA HELPER SPRING KIT	1.00	15.51	15.51

Subtotal for Job #4: 66.51

Parts Total: 29.98
 Labour Total: 102.00
 Sublet Total: 0.00
 Extras Total: 18.60
WORK ORDER TOTAL: 150.58

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 74032



Customer #: 54943
 LITTLEPAGE, DONALD



Customer Signature : _____

Date: 02 Jul 2024

W/O: 74032



Customer #: 54943
LITTLEPAGE, DONALD

