

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1973566
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKB28SK090689
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT26EV-94
JUSTIN D. D THOMPSON		DEALER RO #	74040
11400 STATE RD 68		CLAIM START DATE	07/03/2024
Elberfeld, IN 47613		CLAIM END DATE	01/01/1900
USA			

Retail Date of Purchase	06/28/2024	WARRANTY EXPIRATION DATE	06/28/2025
--------------------------------	------------	---------------------------------	------------

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description	
	70-167-24-00-002001	Water Heater Door - Appliances/Water Heater (Suburban)/Repair/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2024-07-03 11:12:10 :: WATER HEATER DOOR HITTING FLANGE Water heater door hitting flange Adjuster water heater door and flange		
Model#	Dlr Sub Hrs	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	Appr Labor Amt	\$17.00
	Notes		
	Thank you		

Labor

Line# 2	Operation Code	Operational Description	
	20-66-02-17-000672	Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2024-07-03 11:14:47 :: ENTRY DOOR NEEDS ADJUSTED Entry door needs adjusted Adjust door catch so door closes properly.		
Model#	Dlr Sub Hrs	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	Appr Labor Amt	\$34.00
	Notes		

Labor

Line# 3	Operation Code	Operational Description	
	30-101-02-00-001076	Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2024-07-03 11:15:27 :: BATHROOM DOOR HITTING DOOR FRAME Bathroom door hitting frame Adjust bathroom door and frame to close properly.		
Model#	Dlr Sub Hrs	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	Appr Labor Amt	\$34.00
	Notes		

Labor

Line# 4	Operation Code	Operational Description	
	30-103-24-00-001125	Linoleum - Interior/Flooring/Repair/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2024-07-03 11:16:06 :: SILICONE AND RED STAIN ON FLOOR Silicone and red stain on floor Used mineral spirits and rubbing alcohol to remove the stains on the floor		
Model#	Dlr Sub Hrs	Sub Labor Amt	\$85.00

Serial#

Notes

thank you

Appr Hrs

0.50

Appr Labor Amt

\$85.00

Labor

Line# 5

Operation Code

30-100-24-00-001046

Operational Description

Cabinet Door - Interior/Cabinetry/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-07-03 11:16:40 :: STAPLE HOLES IN CABINESTS NEED FILLED Staples holes in cabinet need filled Used fill stik to fill staple holes and blended to match cabinet
Additional Note : bhoffman@americanrvcenter.com, 2024-07-03 11:18:10 :: STAPLE HOLES IN CEILING NEED FILED Staple holes in ceiling need filled Used fil stik and while putty to fill staple holes in ceiling and polished to blend in with the ceiling.

Model#

Dlr Sub Hrs

0.60

Sub Labor Amt

\$102.00

Serial#

Appr Hrs

0.00

Appr Labor Amt

\$0.00

Notes

authorized at 0labor.. factory does not fill holes in the cabintery or drawers
thank you

Submitted	Labor Amt	\$272.00	Approved	Labor Amt	\$170.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$272.00		Total	\$170.00

DEALER

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

DATE

CUSTOMER

SIGNATURE

All repairs described have been inspected and are satisfactory.

DATE