



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74063
Promised Date:
24 JUN 24

CUSTOMER WORK ORDER

WO #: 74063

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: PH
Location: 0716 BH TO CLOSE

Stock #: 11419
Stock Desc: 2025 TT KEYSTONE
SPRINGDALE 310BR
Chassis #: 4YDTSGR29S7100061
Serial #: 4YDTSGR29S7100061
Mileage: 0
Licence:

Invoice #:
Date In: 26 JUN 24
Promised: 31 JUL 24
Date Sched:
Completed: 17 JUL 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*74160 on 08 JUL 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: pdi new unit

CORRECTION: made sure all appliances worked properly all water lines are tight, slides are inline, converter charges, and all outlets work

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: REAR SLIDE ROOM NEEDS ADJUSTED

CAUSE: adjust rear slide room

CORRECTION: loosened slide bolts and moved slide over and lited slide track to level and tightened bolts down and ran slide room in and back out to make sure that it did not move

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	85.00

Subtotal for Job #1: 85.00

Job #2 - Internal

COMPLAINT: REAR ENTRY DOOR NEEDS ADJUSTED

CAUSE: adjust rear door

CORRECTION: removed strike plate from door frame and used air sander to removed excess metal from door frame striker hole then put striker plate back in and adjusted then door was able to shut



Customer #: 1000
BASDENS AMERICAN RV,





Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	N/C
Subtotal for Job #2:			0.00

Job #3 - Internal

COMPLAINT: FRONT ENTRY DOOR NEEDS ADJUSTED

CAUSE: Adjust front door

CORRECTION: opened door and removed striker plate and bent metal in and put back on door and door closed fine

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	N/C
Subtotal for Job #3:			0.00

Job #4 - Warranty

COMPLAINT: LIVING ROOM CABINETS DOORS NEED ADJUSTED

CAUSE: adjust the living room cabinet doors

CORRECTION: the doors were tuching in the middle and when opening one the other would open and i loosened screws and opened door, put shim in the middle, closed door, and tightened screws

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	34.00
Subtotal for Job #4:			34.00

Job #5 - Internal

COMPLAINT: BATHROOM DOOR WILL NOT LATCH

CAUSE: bathroom door would not latch

CORRECTION: i removed striking plate and sanded the hole out a little more and made the striking plate come out a little bit more the where the door could latch properly

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	N/C
Subtotal for Job #5:			0.00

Parts Total:	0.00
Labour Total:	119.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	119.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer Signature : _____

Date: 17 Jul 2024

W/O: 74063
Promised Date: 31 JUL 24



Customer #: 1000
BASDEN'S AMERICAN RV,



Promised Date: 31 JUL 24

