

Pre-Authorization

Pre-Authorization number PA03731944 Reference no: 74071 Status: Approved Approved by papca Approved date 9/4/2024
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGL26S7100138
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	4204306B	Detector, LP - Rej	0.00	0.20	0.20		1	0.20	Complaint:LP DETECTOR WILL NOT RESET Cause:lp detector Correction:lp detector keeps going off it is flashing red and green which means fault and nothing is on,replaced lp detector wired new one up,all good. KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only)

Pre-Authorization number PA03731944 0.20

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company