



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74075
Promised Date:
24 JUL 24



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 74075

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: PH

Location: 0701 BH SENT IN PREAUTH

Stock #: 11415

Stock Desc: 2024 TT KEYSTONE

SPRINGDALE 1800BH

Chassis #: 4YDTSGG18RW104967

Serial #: 4YDTSGG18RW104967

Mileage: 0

Licence:

Invoice #:

Date In: 26 JUN 24

Promised: 31 JUL 24

Date Sched:

Completed: 10 JUL 24

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*74161 on 08 JUL 24

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER - 3 HR PDI

CAUSE: Checked appliances, brakes, tire pressure, torqued lugs, checked electrical system, and plumbing system checked cabinets and drawers. Filled and drained holding tanks. Filled l.p and ran l.p. drop test. Installed battery box.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: BATTEN STRIP ABOVE SINK IS HANGING DOWN FROM CEILING

CAUSE: Plastic track that the batten strip secures to was bent. Straightened track and secured batten strip.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	34.00

Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: GLUE ON FLOOR IN FRONT OF BATHROOM

CAUSE: Took a rag with mineral spirits and removed glue.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------

Printed On: 7/10/2024 9:55:06AM

© 2024 Integrated Dealer Systems



Z990 MISCELLANEOUS REPAIR ZMS 34.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: Placed a wood block at the top and bottom of the door and closed. Took a hammer and moved latch over from door. Door shuts easily.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	51.00

Subtotal for Job #3: 51.00

Job #4 - Warranty

COMPLAINT: ROOF NEEDS DICOR

CAUSE: Applied dicor to roof as needed

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	68.00

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	4.00	7.31	29.24

Subtotal for Job #4: 97.24

Parts Total:	29.24
Labour Total:	187.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	216.24

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Jul 2024

W/O: 74075
Promised Date: 31 JUL 24



Customer #: 1000
BASDENS AMERICAN RV,

