



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74079
Promised Date:
24 JUL 24

CUSTOMER WORK ORDER

WO #: 74079

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0715 CHECK PREAUTH

Stock #: 11422
Stock Desc: 2025 TT KEYSTONE
COUGAR HALF-TON 25FKD
Chassis #: 4YDTCGM28SV500287
Serial #: 4YDTCGM28SV500287
Mileage: 0
Licence:

Invoice #:
Date In: 27 JUN 24
Promised: 31 JUL 24
Date Sched:
Completed: 15 JUL 24
Warr. Date:



Customer #: 1000
BASDEN'S AMERICAN RV,



Job #PDINTT - Internal

Transferred to BAS*74162 on 08 JUL 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: BATTEN STRIP IN FRONT COMPARTMENT IS LOOSE

CAUSE: Batten strip loose in front compartment

CORRECTION: Reattach strip with staples to secure it

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	17.00

Subtotal for Job #1: 17.00

Job #2 - Warranty

COMPLAINT: FRONT COMPARTMENT DOOR WONT LATCH

CAUSE: Front compartment door won't latch

CORRECTION: Reposition latch and tighten nut and screw

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	340.00





Subtotal for Job #2: 340.00

Job #3 - Warranty

COMPLAINT: CROWN MOULDING LOOSE IN PANTRY

CAUSE: Crown molding in pantry loose

CORRECTION: Staple loose crown molding in pantry

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	0.00
Z990	MISCELLANEOUS REPAIR	JH	17.00

Subtotal for Job #3: 17.00

Job #4 - Warranty

COMPLAINT: PANTRY/ENTERTAINMENT DOOR WILL NOT LATCH

CAUSE: Pantry/ entertainment door won't latch

CORRECTION: Tighten screws and Adjust latch to allow door to close properly.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00

Subtotal for Job #4: 34.00

Job #5 - Warranty

COMPLAINT: ADJUST ENTRY DOOR

CAUSE: Adjust entry door to close

CORRECTION: Adjusted the catch to allow door to close properly

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00

Subtotal for Job #5: 34.00

Job #6 - Warranty

COMPLAINT: THE BLACK WATER TANK FLUSH HAS A BLOCKAGE

CAUSE: Black water tank flush has a blockage

CORRECTION: The vacuum breaker valve plumbed backward, reverse lines and works properly

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	0.00
Z990	MISCELLANEOUS REPAIR	JH	34.00

Parts				
Part #	Description	Qty	Price	Total
72-0839	Fresh Water Adapter Fitting; BestPEX; 1/2 Inch PEX x 1/2 Inch Female Pipe Thread Plastic Swivel End Nut	1.00	4.36	4.36
681487	1/2" BARB X 1/2 FPT SWIVEL CONE	1.00	2.08	2.08

Subtotal for Job #6: 40.44

Job #7 - Warranty

COMPLAINT: THE ENTRY DOOR TO THE BEDROOM NEEDS TO BE ADJUSTED



CAUSE: Entry door to bedroom needs adjusted

CORRECTION: Take door catch off and use a burr to grind out to make room for catch to latch the door properly.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JH	34.00
Subtotal for Job #7:			34.00

Parts Total:	6.44
Labour Total:	510.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	516.44

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 15 Jul 2024

Customer Signature : _____

W/O: 74079
Promised Date: 31 JUL 24



Customer #: 1000
BASDEN'S AMERICAN RV,

