

**RE: 11244 - 2023 TT RIVERSIDE RV INTREPID 210 Ser#: 59CCC2328PL006536, RO 74096**

Warranty @Riverside RV <warranty@goriversiderv.com>

Mon 7/8/2024 10:00 AM

To: Ben Hoffman <bhoffman@americanrvcenter.com>

Auth.# 070824-3 for – 1.50 hrs. labor to Remove kinks

Please order parts needed from our parts department at:

parts@goriversiderv.com

Thank you and have a great day,

Laura Kay Hill

260-499-4578

Ext. 110

Riverside RV

1775 E US 20

LaGrange, IN46761

**From:** Ben Hoffman <bhoffman@americanrvcenter.com>

**Sent:** Wednesday, July 3, 2024 4:54 PM

**To:** Warranty @Riverside RV <warranty@goriversiderv.com>

**Subject:** 11244 - 2023 TT RIVERSIDE RV INTREPID 210 Ser#: 59CCC2328PL006536, RO 74096

Good afternoon

1. FRESH TANK WILL NOT FILL ABOVE 1/3

a. fresh tank it not venting to fill

b. took out fill and traced to tank and found vent line was kinked, took off of tank and cut out kink and put back in place, filled with water and it did it again, found another kink under false floor going through real floor and pulled and it vents now, couldnt get pic under false floor i barley got my hand in to pull., patched places where i had to cut to trace vent line.

i. LABOR 2.00

BEN HOFFMAN

WARRANTY/SERVICE

AMERICAN RV CENTER

600 EAST BASELINE RD

EVANSVILLE, IN 47725

PH. 812-867-5200 EXT 263

FAX. 812-868-1012

EMAIL. [BHOFFMAN@AMERICANRVCENTER.COM](mailto:BHOFFMAN@AMERICANRVCENTER.COM)

**\*\*Our phone system does not activate until 9 A.M. Central \*\***

**I'm not yelling at you.our system only recognizes capitol letters.**