



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74110
Promised Date:
24 JUL 24

CUSTOMER WORK ORDER

WO #: 74110

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0718 BH TO CLOSE

Stock #: 11426
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 211BH
Chassis #: 5ZT2CAKB0SU044112
Serial #: 5ZT2CAKB0SU044112
Mileage: 0
Licence:

Invoice #:
Date In: 02 JUL 24
Promised: 31 JUL 24
Date Sched:
Completed: 18 JUL 24
Warr. Date: 27 JUL 24

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER - 4 HR PDI
25 CATALINA SY044112

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: J WRAP ON OFF DOOR SIDE NEEDS SCREWED IN

CAUSE: j wrap

CORRECTION: screwed back in screw on j wrap.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	8.50

Subtotal for Job #1: 8.50

Job #2 - Warranty

COMPLAINT: RIGHT FRONT CAB LIGHT NOT WORKING

CAUSE: wire not hooked up

CORRECTION: took off lens and 2 screws and found ground wire was not hooked up, rehooked wires back up and crimped, secured light and resealed.



Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 74110
Promised Date: 31 JUL 24



Customer #: 1000
BASDENS AMERICAN RV,



Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00
Subtotal for Job #2:			34.00

Job #3 - Warranty

COMPLAINT: FURNANCE DOES NOT WORK

CAUSE: furnance wont come on

CORRECTION: took panel down to wiring in ac and checked furnance wires for power,no power,took off panel beside furnance and found wires were not hooked up see pictures,hooked up wires and furnance works,put panel back on and on ac,all goog.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	68.00
Subtotal for Job #3:			68.00

Job #4 - Warranty

COMPLAINT: TV HAS NO RECEPTION

CAUSE: no tv channels

CORRECTION: ran tv scan and no tv channels,took out tv booster and found antanna cable and orange cable were in the wrong place,switched the two cables and i got 16 channels.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00
Subtotal for Job #4:			34.00

Parts Total:	0.00
Labour Total:	144.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	144.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 18 Jul 2024

