

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1977574
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAEC1RK008505
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT164BHX
		DEALER RO #	74125
		CLAIM START DATE	07/08/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-62-01-00-000650	Interior Vent Garnish - Exterior/Power Roof Vent (Elixir & Hengs)/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-07-08 15:39:05 :: BATHROOM VENT INSIDE COVER IS BROKEN Bathroom vent trim is broken Put in po sheet for new vent,took pictures.			
Model#		Dlr Sub Hrs	0.10	Sub Labor Amt \$17.00
Serial#		Appr Hrs	0.10	Appr Labor Amt \$17.00
	Notes			
	(Feedback) In order to review this repair, Forest River will need a copy of the Dealer Acceptance Form, as it has not been uploaded to the VIN from Dealer Connect. Please go to the VIN on Dealer Connect and upload the DAF using the Attach Dealer Acceptance Form button. Once it's been uploaded, add a comment to the repair line and acknowledge the line so we can complete the review process.			
	DONE			

Labor

Line# 2	Operation Code	Operational Description		
	70-147-01-11-000016	King Control TV Antenna - Appliances/Television/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-07-08 15:43:04 :: ANTENNA IS MISSING NEED TO INSTALL AN ANTENNA AND NO TV CHANNELS INSTALL NEW ANTENNA			
Model#		Dlr Sub Hrs	1.50	Sub Labor Amt \$255.00
Serial#		Appr Hrs	1.50	Appr Labor Amt \$255.00
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	20-58-24-00-000608	Metal - Aluminum Siding, each sheet - Exterior/Metal, Aluminum Siding/Repair/ No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-07-08 15:45:38 :: BELOW THE VIN TAG THE SEALER IS MISSING Sealer has a void for water to enter Took picture of the sealer then got sealer from the parts department. Applied the sealer below the vin tag. Checked the whole camper for anymore voids in the silver sealer.			
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$34.00
	Notes			

Labor

Line# 4

Operation Code
30-101-24-00-001074

Operational Description
Interior Door Jamb, U-Channel, Casing, Frame - Interior/Interior Doors/Repair/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-07-08 15:46:52 :: THE DOOR FRAME TO THE BATHROOM YOU CAN SEE WOOD ON THE RIGHT SIDE Bathroom plastic door frame was loose and could see the stud. Took pictures of the door frame and the wall stud showing. Got the same style of screw then screwed the screw into the plastic door frame. Now the door frame is tight and no wall stud is showing.

Model#

Dlr Sub Hrs 0.30

Sub Labor Amt \$51.00

Serial#

Appr Hrs 0.30

Appr Labor Amt \$51.00

Notes

Submitted	Labor Amt	\$357.00	Approved	Labor Amt	\$357.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$357.00		Total	\$357.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.