



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74125
Promised Date:
24 JUL 24



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 74125

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag: PH - ANTENNA ORDERED 7-8-24
Author: PH
Location: 0717 BH TO CLOSE

Stock #: 11428
Stock Desc: 2024 TT COACHMEN
CATALINA SUMMIT SERIES 164BHX
Chassis #: 5ZT2CAEC1RK008505
Serial #: 5ZT2CAEC1RK008505
Mileage: 0
Licence:

Invoice #:
Date In: 03 JUL 24
Promised: 31 JUL 24
Date Sched:
Completed: 19 JUL 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 3 HR PDI

CAUSE: New pdi

CORRECTION: Checked the psi in the tires and was set to 65psi same as data tag. Checked and set the lug nut torque to 110ftlbs. Hooked up a test battery then, Jacked up the camper to check the brakes and breakaway switch, running lights. Filled the 20lb lp tank and mounted the battery box. Plugged in the shore power cord. Ran down the stab jacks. Turned the mini fridge on to cool. Filled the fresh tank 1/3 full then flushed the antifreeze thru the kitchen faucet, shower, and the toilet. Checked the 110v outlets and gcfi outlets, usb ports. Tested the antenna signal with a tv but there was no antenna. Checked the radio. Put in po sheet for an antenna and bathroom vent. Setup for lp drop test and check for leaks, let the furnace and water heater run to adjust the wc. Turned the valves at the water heater and water pump. After 30 mins checked for hot water from the kitchen faucet and shower. Hooked up the city water connection and filled up the grey tank to check the sensors. Hooked up to the black tank flush to fill the black tank reading. Ran the awning out and in. Checked the windows exits and blinds. Checked the hood range light, fan and stove. Checked the bathroom fan and found the trim is broken, put in po sheet for new vent. Turned on the ac and let it run for 1 hr. Checked the converter output, smoke alarm, lp detector. Drained the black and grey, fresh tanks.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C
F100359506	SILICONE, NEUTRAL CURE SILICONE 10.3	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	1.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: BATHROOM VENT INSIDE COVER IS BROKEN


CAUSE: Bathroom vent trim is broken

CORRECTION: Put in po sheet for new vent, took pictures.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------





Z990	MISC LABOUR CODE (EXTERNAL)	JG	15.30
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	1.70

Parts				
Part #	Description	Qty	Price	Total
47-0305	VENTLINE GARNISH - BIRCH WHITE	1.00	5.70	5.70
Subtotal for Job #1:				22.70

Job #2 - Warranty
 ANTENNA IS MISSING

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	255.00

Parts				
Part #	Description	Qty	Price	Total
F100334681	EXTENSION, ANTENNA 144" AXT144	1.00	4.75	4.75
F100395205	BASE ONLY TO RVTV1TW ANTENNA	1.00	25.62	25.62
F100334599	ANTENNA, OMNI DIRECTIONAL	1.00	36.05	36.05

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-ANTENNA PARTS	1.00	26.25	26.25
Subtotal for Job #2:				347.67

Job #3 - Warranty
 COMPLAINT: BELOW THE VIN TAG THE SEALER IS MISSING

CAUSE: Sealer has a void for water to enter

CORRECTION: Took picture of the sealer then got sealer from the parts department. Applied the sealer below the vin tag. Checked the whole camper for anymore voids in the silver sealer.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	34.00
Subtotal for Job #3:			34.00

Job #4 - Warranty
 COMPLAINT: THE DOOR FRAME TO THE BATHROOM YOU CAN SEE WOOD ON THE RIGHT SIDE

CAUSE: Bathroom plastic door frame was loose and could see the stud.

CORRECTION: Took pictures of the door frame and the wall stud showing. Got the same style of screw then screwed the screw into the plastic door frame. Now the door frame is tight and no wall stud is showing.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	51.00
Subtotal for Job #4:			51.00

Parts Total:	72.12
Labour Total:	357.00
Sublet Total:	0.00
Extras Total:	26.25
WORK ORDER TOTAL:	455.37



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Jul 2024

W/O: 74125
Promised Date: 31 JUL 24



Customer #: 1000
BASDEN'S AMERICAN RV,

