



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74180
Promised Date: 24 JUL 24

CUSTOMER WORK ORDER

WO #: 74180

Customer: 55014 - DEKEMPER, DONNA
- 930-204-1335

Tag:
Author: PH
Location: 0805 CHECK PREAUTH

Stock #: 11353
Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 1750RD
Chassis #: 4YDTS GG15RW103341
Serial #: 4YDTS GG15RW103341
Mileage:
Licence:

Invoice #: 407439
Date In: 09 JUL 24
Promised: 31 JUL 24
Date Sched:
Completed: 31 JUL 24
Warr. Date: 26 JUL 24



Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT FINAL PDI ON NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from showroom. Installed new battery. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 75 psi. Checked awning and roof. Checked all interior lights. Added water to fresh water tank and checked water pump. Connected to city water and flushed water lines and faucets. Performed LP drop test and set LP pressure at 10 in.wc. Checked operation of AC, Refrig, Furnace, Water Heater and Microwave. Checked TV Antenna with test TV. Dumped holding tanks and moved unit to washbay area.

Labor Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #1 - Internal

COMPLAINT: BRAND MOTION CAMERA INSTALLED

CAUSE: 1 BRAND MOTION CAMERA INSTALLED

CORRECTION: Removed Furrion Camera mount on rear of unit. Unit came without installation instructions. Cut off factory plug on wire harness. Spliced factory wires to new backup camera. Cleared out wood support to allow wires to be stuffed into rear wall. Checked operation of backup camera. OK. Mounted backup camera to rear of unit. Sealed around camera mount. Checked operation after complete mounting. Moved unit to wash bay area.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts Part #	Description	Qty	Price	Total
8952	BRAND MOTION 7" CAMERA SYSTEM	1.00	N/C	N/C

Customer #: 55014
DEKEMPER, DONNA



Subtotal for Job #1: 0.00

Job #MONSTER - Internal

COMPLAINT: MONSTER SEAL IN ALL TIRES

CAUSE: MONSTER MONSTER SEAL IN ALL TIRES

CORRECTION: Added Monster Seal to both tires on ground.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #MONSTER: 0.00

Job #2 - Internal

COMPLAINT: HAVE WASHBAY MAXX GUARD CAMPER

CORRECTION: HAD WASBAY MAXX GUARD UNIT

Subtotal for Job #2: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts Part #	Description	Qty	Price	Total
40052	40052 BRASS W.P. REGULATOR	1.00	N/C	N/C
40280	TST 2PLY TOILET TISSUE, INDIVIDUAL R	4.00	N/C	N/C
22596	22596 50' CAMCO EVOFLEX HOSE	1.00	N/C	N/C
39390	39390 20' RHINO X SEWER HOSE KIT	1.00	N/C	N/C
41601	41601 8-4OZ BOTTLES TST HIBISCUS BRE	1.00	N/C	N/C
5487	A10-1530HVP 15M - 30F ADAPTER CORD	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH ADDED ON DELIVERY DAY BUT IT IS NOT ON THE DRP

CAUSE: e2 hitch

CORRECTION: set up brackets on camper and set up hitch on truck, tightened everything down and put bars on and adjusted l brackets 2 holes and tightened all good.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #3 - Warranty

COMPLAINT: THE AWNING SWITCH IS POKING OUT



W/O: 74180
Promised Date: 31 JUL 24



Customer #: 55014
DEKEMPER, DONNA





CAUSE: Awning switch pops out on bottom

CORRECTION: Took out switch and found bottom clip is smashed, put switch in and put cotter pin inclined to hold bottom switch in.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	34.00
Subtotal for Job #3:			34.00

Job #4 - Warranty

COMPLAINT: THE AWNING IS NOT ADJUSTED RIGHT

CAUSE: Awning adjustment locks don't work

CORRECTION: Locks came apart on both sides, took out and put back together and installed them back in and it slides up and down to pitch awning.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	34.00
Subtotal for Job #4:			34.00

Job #BCWT - Internal

COMPLAINT: BRAKE CONTROL & WIRING - PICKUP TRUCK ONLY

CAUSE: 1/2 CUSTOMER AND 1/2 I DEALER OPTION PER CHAD

CORRECTION: INSTALLED BRAKE CONTROL AND WIRING. USED A OEM TYPE HARNESS AND CHECKED 7-WAY OUTPUT.

Labor			
Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C
Z990	MISCELLANEOUS REPAIR		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts				
Part #	Description	Qty	Price	Total
51146	TRIFLEX NEXT GENERATION BRAKE CONTRO	0.50	N/C	N/C
51146	TRIFLEX NEXT GENERATION BRAKE CONTRO	0.50	N/C	N/C
81794	81794 09-21 FORD HARNESS	0.50	N/C	N/C
81794	81794 09-21 FORD HARNESS	0.50	N/C	N/C
Subtotal for Job #BCWT:				0.00

Job #5 - Internal

PART FOR CUSTOMER



W/O: 74180
Promised Date: 31 JUL 24

Parts	Description	Qty	Price	Total
Part # 53388	53388 LIBATC OVER DOOR HANGER	1.00	N/C	N/C
Subtotal for Job #5:				0.00

Job #6 - Internal

COMPLAINT: CHRIS HAD TO LEAVE, SHOW CUSTOMER HITCH WORK

CORRECTION: SHOWED CUSTOMER HOW TO USE THE HITCH AND BRAKE CONTROL.

Labor	Description	Mechanic	Total
Code Z990	MISCELLANEOUS REPAIR	GAH	N/C
Subtotal for Job #6:			0.00

Parts Total: 0.00
Labour Total: 68.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 68.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Aug 2024



Customer #: 55014
DEKEMPER, DONNA

