

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1984554
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CASB9RU043096
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT271DBS-8
LACEY A MONYHAN		DEALER RO #	74210
4812 E STATE RD		CLAIM START DATE	07/15/2024
Haubstadt, IN 476396		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	06/08/2024	WARRANTY EXPIRATION DATE	06/08/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operation Description		
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-07-15 10:11:25 :: THE SHOWER IS LEAKING WHERE THE HOSE CONNECTS TO THE FIXTURE. NEEDS FIXED AND RESEALED BACK UP shower leaking behind faucet, took apart and connections were leaking, took cold and hot side off and replaced cone washers and tested for leaks, installed faucet back in place and sealed.			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$68.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$68.00
	Notes			
	AUTHORIZED AS REQUESTED.			

Labor

Line# 2	Operation Code	Operational Description		
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-07-15 10:12:19 :: TOILET IS LEAKING AT THE VALVE. HE HAS TO CONSISTENTLY TIGHTEN IT water line leaking at valve took pics took off line and replaced cone washer put back on and tested,no leaks.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
	Notes			
	AUTHORIZED AS REQUESTED.			

Labor

Line# 3	Operation Code	Operational Description		
	10-9-15-00-000168	Polymax Underbelly - Frame & Chassis/Levelers, Underbelly/Repair or Replace/ No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-07-15 10:13:06 :: HOLE NEEDS SEALED UNDER THE KITCHEN SINK BEHIND THE FAKE WALL WHERE A BRAIDED LINE RUNS THROUGH THE FLOOR. HE STATES THAT THE LINE IS FRAYED NOW TOO. hole in floor undrneath camper sealed hole with sprayfoam,let dry and painted black.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$17.00	
Serial#	Appr Hrs	0.10	Appr Labor Amt \$17.00	
	Notes			
	AUTHORIZED AS REQUESTED.			

Submitted	Labor Amt	\$119.00
	Parts & Freight	\$0.00
	Total	\$119.00

Approved	Labor Amt	\$119.00
	Parts & Freight	\$0.00
	Total	\$119.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	